

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : Laguna AAWater Corporation

ADDRESS : G/F One Evotech Building, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna 4026

ATTENTION : Santa Rosa City Health Office I

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 20

TOTAL PARAMETERS TESTED: 3

ANALYSIS DATE(S) : 06/02/2026-06/23/2026

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER		
			COLIFORM ^A		HPC ^B (CFU/mL)
			TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. BIÑAN					
06/04/2026 15:11	S26-3450	Laguna Wellfield I	ABSENCE	ABSENCE	< 1
BRGY. CAINGIN					
06/02/2026 11:21	S26-3368	Water Pump, Block 57, Phase I, Southville	ABSENCE	ABSENCE	1
06/02/2026 12:06	S26-3369	Block 25 Lot 7, Phase 3, Southville	ABSENCE	ABSENCE	< 1
06/02/2026 11:48	S26-3371	Drinking Fountain, Southville 4 National Highschool	ABSENCE	ABSENCE	< 1
BRGY. KANLURAN					
06/02/2026 10:29	S26-3365	Gate Entrance, Alfonso Homes I	ABSENCE	ABSENCE	< 1
BRGY. MALUSAK					
06/02/2026 09:40	S26-3370	Drinking Fountain, I, Central I Elementary	ABSENCE	ABSENCE	< 1
06/02/2026 09:52	S26-3364	Canteen, Santa Rosa City Hall, J.P. Rizal Boulevard	ABSENCE	ABSENCE	248
BRGY. SINALHAN					
06/02/2026 09:03	S26-3362	Block 8 Lot 16, Bayshore III	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

M. Benojar
MARVIN JASPER G. ABENOJAR
Microbiology Unit Manager

APPROVED BY:

K. Y. Alday
KRISTEEN Y. ALDAY, RCH
Laboratory Service Manager
License No(s). (PRC 0013295)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER		
			COLIFORM ^A		HPC ^B (CFU/mL)
			TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. TAGAPO					
06/09/2026 09:58	S26-3537	#6031 JP Rizal Boulevard	ABSENCE	ABSENCE	<1
06/09/2026 10:06	S26-3539	Block 1 Lot 18, Fairfield of Margana Subdivision	ABSENCE	ABSENCE	<1
06/09/2026 10:30	S26-3546	Water Pump, Rosewood Homes I	ABSENCE	ABSENCE	28
06/23/2026 13:28	S26-3876	Block 3 Lot 31, Rosewood Homes I	ABSENCE	ABSENCE	27
06/09/2026 09:21	S26-3538	Pump House Eye Wash, Buena Rosa 1 Subdivision	ABSENCE	ABSENCE	<1
06/09/2026 09:40	S26-3540	Block 14 Lot 17, Buena Rosa X	ABSENCE	ABSENCE	<1
06/09/2026 11:39	S26-3541	Cistern Tank, SM Santa Rosa	ABSENCE	ABSENCE	<1
06/09/2026 11:46	S26-3542	Admin Pantry, SM Santa Rosa	ABSENCE	ABSENCE	<1
06/23/2026 13:47	S26-3877	Cistern Tank, Robinson's Mall	ABSENCE	ABSENCE	8
06/23/2026 13:55	S26-3878	Pepa Wings, Robinson's Mall	ABSENCE	ABSENCE	<1
06/17/2026 13:54	S26-3789	Water Pump, Metrogate Heritage Subdivision	ABSENCE	ABSENCE	<1
06/17/2026 14:10	S26-3790	Clubhouse, Metrogate Heritage Subdivision	ABSENCE	ABSENCE	<1

REMARKS: Sample collection was performed by LAWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **NA** – Not Applicable (-) Not performed

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A**– Enzyme Substrate; **B**– Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 24th Edition

NOT VALID WITHOUT QR CODE



REVIEWED BY:

M. Abenojar
MARVIN JASPER G. ABENOJAR
Microbiology Unit Manager

APPROVED BY:

K. Alday
KRISTEEN Y. ALDAY, RCH
Laboratory Service Manager
License No(s). (PRC 0013295)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph
CUSTOMER NAME : Laguna AAWater Corporation

ADDRESS : G/F One Evotech Building, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna 4026

ATTENTION : Santa Rosa City Health Office II

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 39

TOTAL PARAMETERS TESTED : 3

ANALYSIS DATE(S) : 06/02/2026-06/17/2026

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATIOHN	PARAMETER		
			COLIFORM ^A		HPC ^B (CFU/mL)
			TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. BIÑAN					
06/04/2026 15:11	S26-3450	Laguna Wellfield I	ABSENCE	ABSENCE	< 1
BRGY. BALIBAGO					
06/02/2026 12:34	S26-3363	#4354 Facundo Compound	ABSENCE	ABSENCE	< 1
06/02/2026 15:04	S26-3373	Clubhouse, South Hampton Residences	ABSENCE	ABSENCE	47
06/17/2026 14:21	S26-3788	Block 5 Lot 25, JB Village	ABSENCE	ABSENCE	< 1
06/22/2026 14:21	S26-3831	Cistern Tank, Waltermart Santa Rosa	ABSENCE	ABSENCE	< 1
06/22/2026 14:13	S26-3832	2nd Floor Faucet, Waltermart Santa Rosa	ABSENCE	ABSENCE	15
BRGY. DILA					
06/17/2026 12:38	S26-3778	Water Pump, Phase IIIE, Mabuhay Homes 2000, Golden City Subdivision	ABSENCE	ABSENCE	< 1
06/17/2026 12:47	S26-3779	Block 2 Lot 10, Phase IIIE, Mabuhay Homes 2000, Golden City Subdivision	ABSENCE	ABSENCE	< 1
06/17/2026 12:00	S26-3780	Water Pump, Block 12, Phase IIE, Mabuhay Homes 2000	ABSENCE	ABSENCE	< 1
06/17/2026 12:10	S26-3781	Block 13 Lot 5, Phase 2E, Mabuhay Homes 2000	ABSENCE	ABSENCE	< 1
06/02/2026 14:52	S26-3374	Clubhouse, Alabaster St., Villa Esmeralda	ABSENCE	ABSENCE	< 1
06/17/2026 13:09	S26-3782	Drinking Fountain, Dila Elementary School	ABSENCE	ABSENCE	< 1
BRGY. DITA					
06/17/2026 11:18	S26-3783	Block 19 Lot 11, New Santa Rosa Homes	ABSENCE	ABSENCE	< 1
06/17/2026 11:00	S26-3784	Water Tank, SolCar Ville Subdivision	ABSENCE	ABSENCE	< 1
06/17/2026 10:51	S26-3785	Block 3 Lot 7, SolCar Ville Subdivision	ABSENCE	ABSENCE	< 1
06/17/2026 10:25	S26-3786	#1780, National Road	ABSENCE	ABSENCE	< 1
06/17/2026 09:52	S26-3791	R & B Ice Plant, Inc.	ABSENCE	ABSENCE	< 1
06/02/2026 14:40	S26-3375	Gate Entrance, San Lorenzo Royale	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE

REVIEWED BY:

Mabenojar
MARVIN JASPER G. ABENOJAR
 Microbiology Unit Manager

APPROVED BY:

Kristeen Y. Alday
KRISTEEN Y. ALDAY, RCh
 Laboratory Service Manager
 License No(s). (PRC 0013295)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis.

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER		
			COLIFORM ^A		HPC ^B (CFU/mL)
			TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. DON JOSE					
06/15/2026 13:46	S26-3658	Church, Block 108, Phase V, Laguna Bel-Air	ABSENCE	ABSENCE	9
06/15/2026 15:05	S26-3657	Clubhouse, Phase I, Laguna Bel-Air	ABSENCE	ABSENCE	< 1
06/15/2026 14:53	S26-3661	Block 47 Lot 12, Laguna Bel-Air IV	ABSENCE	ABSENCE	< 1
06/15/2026 10:55	S26-3652	Clubhouse. Phase IV-B, Santa Rosa Village I	ABSENCE	ABSENCE	< 1
06/15/2026 11:10	S26-3653	Clubhouse, Santa Rosa Village II	ABSENCE	ABSENCE	< 1
06/15/2026 12:51	S26-3654	Pump 9 & 10, Santa Rosa Estates I	ABSENCE	ABSENCE	< 1
06/15/2026 13:10	S26-3655	Clubhouse, Santa Rosa Estates I	ABSENCE	ABSENCE	< 1
06/15/2026 15:28	S26-3662	Drinking Fountain, Don Jose National High School	ABSENCE	ABSENCE	< 1
BRGY. MACABLING					
06/09/2026 09:03	S26-3548	Block 4 Lot 44, Phase 2, Buena Rosa IX Subdivision	ABSENCE	ABSENCE	30
06/09/2026 08:44	S26-3545	Clubhouse, Corinthian Homes Subdivision	ABSENCE	ABSENCE	12
BRGY. MALITLIT					
06/17/2026 10:00	S26-3787	Guardhouse, Casan Residencia Subdivision	ABSENCE	ABSENCE	< 1
06/02/2026 14:26	S26-3377	Gate Entrance Guardhouse, Terra Fortuna	ABSENCE	ABSENCE	< 1
06/02/2026 14:13	S26-3376	Block 1 Lot 17, Villa Las Casas	ABSENCE	ABSENCE	< 1
BRGY. POOC					
06/02/2026 10:50	S26-3366	Water Pump, Villa Mercedes	ABSENCE	ABSENCE	< 1
06/02/2026 11:01	S26-3367	Block 2 Lot 1, Villa Mercedes	ABSENCE	ABSENCE	< 1
BRGY. PULONG STA. CRUZ					
06/22/2026 12:18	S26-3833	Water Pump, Buklod Diwa	ABSENCE	ABSENCE	< 1
06/22/2026 12:00	S26-3834	Manzano Residence, Buklod Diwa	ABSENCE	ABSENCE	< 1
06/22/2026 14:36	S26-3835	Wash Area, Pulong Sta. Cruz Elementary School	ABSENCE	ABSENCE	< 1
BRGY. SANTO DOMINGO					
06/15/2026 12:31	S26-3656	Clubhouse, Santa Rosa Estates II	ABSENCE	ABSENCE	< 1
06/15/2026 11:34	S26-3663	Water Pump, Brgy. Sto. Domingo	ABSENCE	ABSENCE	< 1
06/15/2026 11:56	S26-3664	Tope Residence, Brgy. Sto. Domingo	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE

REVIEWED BY:

Mabenojar
MARVIN JASPER G. ABENOJAR
 Microbiology Unit Manager

APPROVED BY:

Kristeen Y. Alday
KRISTEEN Y. ALDAY, RCh
 Laboratory Service Manager
 License No(s). (PRC 0013295)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis.

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

REMARKS: Sample collection was performed by LAWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC – Heterotrophic Plate Count; CFU – Colony Forming Units; NA – Not Applicable (-) Not performed

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: A- Enzyme Substrate; B– Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 24th Edition

NOT VALID WITHOUT QR CODE



REVIEWED BY:


MARVIN JASPER G. ABENOJAR
Microbiology Unit Manager

APPROVED BY:


KRISTEEN Y. ALDAY, RCh
Laboratory Service Manager
License No(s). (PRC 0013295)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : Laguna AAWater Corporation

ADDRESS : G/F One Evotech Building, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna 4026

ATTENTION : N/A

SUMMARY OF LABORATORY ANALYSIS

SAMPLE CODE(S) : S26-3451

DATE/TIME SUBMITTED : 06/04/2026 15:36

DATE/TIME COLLECTION : 06/04/2026 13:25

COLLECTED BY : Jonnel S. Mercado

NO. OF SAMPLES : 1

TOTAL PARAMETERS TESTED : 4

SAMPLE LOCATION : BOOSTER 1, LAGUNA TECHNOPARK INC., SANTA ROSA CITY, LAGUNA

SAMPLE CHARACTERISTICS : 100 mL water sample in clear and sterile glass container with 3% sodium thiosulfate.

PARAMETER(S)	UNIT(S)	RESULT(S)	PNSDW LIMIT(/S)	METHOD(S)	ANALYSIS	
					DATE	BY
*Residual Chlorine	mg/L	0.60	0.30 – 1.50	4500-Cl-G.DPD Colorimetric	06/04/2026	JSM
Total Coliform	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert- 18®)	06/04/2026	ABG
Thermotolerant Coliform / <i>Escherichia coli</i>	Coliforms/100 mL	ABSENCE	ABSENCE	9223B. Enzyme Substrate Test (Colilert- 18®)	06/04/2026	ABG
Heterotrophic Plate Count (HPC) ^A	Colony Forming Unit (CFU)/mL	< 1	< 500 (cfu/mL)	9215B. Pour Plate Method	06/04/2026	ABG

REMARKS: Sample collection was performed by LAWC accredited sampler and was analyzed as submitted.

NOTE: ^A – Method is not part of DENR-ELR Recognized Parameters

*-Performed Onsite

DEVIATIONS: No deviations noted on sample collection and submission.

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 24th Edition

NOT VALID WITHOUT QR



REVIEWED BY:

Marvin Jasper G. Abenojar
MARVIN JASPER G. ABENOJAR
Microbiology Unit Manager

APPROVED BY:

Kristeen Y. Alday, RCh.
KRISTEEN Y. ALDAY, RCh.
Laboratory Services Manager
License No(s). (PRC 0013295)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis