

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II (CHO-2)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 20

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 02/11/2020-02/27/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. MAMATID							
02/11/2020 11:19	S20-0994	Water Pump, Buena Rosario Subdivision	7.54 / 29.1	0.43	ABSENCE	ABSENCE	-
02/11/2020 11:32	S20-0995	Block 3 Lot 3, Buena Rosario Subdivision	7.75 / 29.0	0.08	ABSENCE	ABSENCE	-
02/11/2020 12:26	S20-0988	Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes	7.64 / 29.0	0.35	ABSENCE	ABSENCE	-
02/11/2020 12:33	S20-0989	Block 101 Lot 20, Guimaras St., Phase 1, Mabuhay City Homes	7.71 / 28.7	0.48	ABSENCE	ABSENCE	-
02/11/2020 10:29	S20-0990	Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes	7.72 / 28.7	0.62	ABSENCE	ABSENCE	-
02/11/2020 10:35	S20-0991	Block 134 Lot 22, Phase 2, Mabuhay City Homes	7.55 / 28.3	0.56	ABSENCE	ABSENCE	-
02/11/2020 10:58	S20-0996	Water Pump, Block 198, Galacia St., Phase 2, Mabuhay City Homes	7.62 / 28.4	0.66	ABSENCE	ABSENCE	-
02/11/2020 10:45	S20-0997	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes	7.56 / 28.6	0.73	ABSENCE	ABSENCE	-
02/26/2020 12:33	S20-1211	Water Pump, Panganig St., Phase 3, Mabuhay City Homes	7.80 / 29.5	0.55	ABSENCE	ABSENCE	-
02/26/2020 12:06	S20-1212	Block 1 Lot 17, Dizon St., Phase 3, Mabuhay City Homes	7.74 / 30.0	0.55	ABSENCE	ABSENCE	-
02/11/2020 12:57	S20-0986	Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	7.64 / 28.4	0.59	ABSENCE	ABSENCE	-
02/11/2020 13:08	S20-0987	Block 19 Lot 13, Malang St., Phase 3 Luxury, Mabuhay City Homes	7.58 / 29.3	0.54	ABSENCE	ABSENCE	-
02/26/2020 12:55	S20-1209	Water Pump, Joshua St., Phase 5, Mabuhay City Homes	7.83 / 30.2	1.00	ABSENCE	ABSENCE	-
02/26/2020 12:59	S20-1210	Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City Homes	7.84 / 29.9	0.62	ABSENCE	ABSENCE	-
02/11/2020 11:49	S20-0992	Water Pump, Phase 1E Mabuhay Executive	7.77 / 31.8	0.64	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR STAMP

ANALYZED BY:

CERTIFIED CORRECT BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C) MDL: NA LOQ: NA	RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
02/11/2020 11:57	S20-0993	Block 236 Lot 9, Phase 1E Mabuhay Executive	7.78 / 28.1	0.49	ABSENCE	ABSENCE	-
BRGY. PULO							
02/26/2020 10:45	S20-1200	Water Pump, Block 12 Lot 22, Cabuyao Central	7.68 / 28.7	0.31	ABSENCE	ABSENCE	-
02/26/2020 10:53	S20-1201	Clubhouse, Narra Avenue, Cabuyao Central	7.94 / 29.2	1.71	ABSENCE	ABSENCE	-
02/26/2020 10:21	S20-1202	Water Pump, Block 11, Willow Park Homes	7.66 / 29.4	0.57	ABSENCE	ABSENCE	-
02/26/2020 10:29	S20-1203	Clubhouse, Willow Park Homes	7.55 / 31.3	0.55	ABSENCE	ABSENCE	-

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR STAMP

ANALYZED BY:

CERTIFIED CORRECT BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I (CHO-1)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 24

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 02/04/2020-02/27/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. BANAY-BANAY							
02/04/2020 08:25	S20-0744	Water Pump, Block 63, Lakeside Nest Subdivision	7.40 / 29.0	0.78	ABSENCE	ABSENCE	-
02/04/2020 08:20	S20-0745	Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision	7.28 / 28.1	0.56	ABSENCE	ABSENCE	-
BRGY. BANLIC							
02/26/2020 11:10	S20-1204	Water Pump, Gran Seville Subdivision	7.71 / 29.0	0.40	ABSENCE	ABSENCE	-
02/26/2020 11:17	S20-1205	Gate Entrance, Gran Seville Subdivision	7.75 / 29.5	0.35	ABSENCE	ABSENCE	-
BRGY. BIGAA							
02/04/2020 08:55	S20-0747	#253 Elsol Subdivision	7.47 / 27.6	0.30	ABSENCE	ABSENCE	-
BRGY. GULOD							
02/11/2020 09:57	S20-0998	Water Pump, Block 12, Noah St., Celestine Ville	7.36 / 28.6	0.13	ABSENCE	ABSENCE	-
02/11/2020 10:07	S20-0999	Guardhouse, Celestine Ville	7.34 / 28.8	0.11	ABSENCE	ABSENCE	-
BRGY. MARINIG							
02/04/2020 10:15	S20-0735	Block 3 Lot 17, Phase 1, Celestine Homes	7.21 / 27.8	0.68	ABSENCE	ABSENCE	-
02/04/2020 10:28	S20-0736	Block 23, Lot 10, Phase 1, Celestine Homes	7.20 / 28.6	0.56	ABSENCE	ABSENCE	-
02/04/2020 11:00	S20-0737	Block 9, Carnation St., Phase 2, Celestine Homes	7.25 / 27.7	0.38	ABSENCE	ABSENCE	-
02/04/2020 14:25	S20-0738	Block 13 Lot 2, Phase 2, Celestine Homes	7.28 / 27.4	0.26	ABSENCE	ABSENCE	-
02/04/2020 09:50	S20-0740	Water Pump, Block 25, Phase 3, Southville	7.23 / 27.5	0.45	ABSENCE	ABSENCE	-
02/04/2020 10:10	S20-0741	Block 19 Lot 33, Phase 3, Southville	7.24 / 27.3	0.30	ABSENCE	ABSENCE	-
BRGY. NIUGAN							
02/04/2020 09:30	S20-0748	Block 2 Lot 6, St. Francis Homes 6	7.40 / 27.8	0.48	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR STAMP

ANALYZED BY:

CERTIFIED CORRECT BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C) MDL: NA LOQ: NA	RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
02/11/2020 09:57	S20-0741	Water Pump, Phase 9, Southville	7.38 / 30.0	0.33	ABSENCE	ABSENCE	-
02/11/2020 09:16	S20-1001	De Guzman Residence, Phase 9, Southville	7.26 / 29.1	0.23	ABSENCE	ABSENCE	-
02/04/2020 09:15	S20-0744	Block 47 Lot 101, Phase 10, Southville	7.39 / 28.8	0.55	ABSENCE	ABSENCE	-
02/04/2020 09:30	S20-0741	Water Pump, Block 45, Phase 8	7.23 / 27.6	0.45	ABSENCE	ABSENCE	-
02/04/2020 09:39	S20-0742	Block 40 Lot 132, Phase 8	7.33 / 27.5	0.32	ABSENCE	ABSENCE	-
02/04/2020 09:00	S20-0743	Water Pump, Block 54, Phase 10, Southville	7.26 / 26.6	0.50	ABSENCE	ABSENCE	-
BRGY. SALA							
02/11/2020 08:47	S20-1002	Gate Entrance, Amaia Scapes	7.13 / 28.1	0.70	ABSENCE	ABSENCE	-
BRGY. SAN ISIDRO							
02/26/2020 11:36	S20-1208	Block 3 Lot 33, Multiland IV	7.68 / 29.0	1.08	ABSENCE	ABSENCE	-
02/26/2020 11:49	S20-1206	Water Pump, San Isidro Heights Subdivision	7.67 / 29.5	1.07	ABSENCE	ABSENCE	-
02/26/2020 11:56	S20-1207	Block 3 Lot 1, San Isidro Heights Subdivision	7.69 / 29.1	1.07	ABSENCE	ABSENCE	-

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric ; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR STAMP

ANALYZED BY:

CERTIFIED CORRECT BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis