

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 23

TOTAL PARAMETERS TESTED : 5


ANALYSIS DATE(S) : 12/03/2021 – 12/08/2021

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. BANAY-BANAY							
12/03/2021 12:55	S21-8104	Water Pump, Block 63, Lakeside Nest Subdivision	7.96 / 28.2	0.07	ABSENCE	ABSENCE	320
12/03/2021 12:41	S21-8105	Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision	7.57 / 28.6	0.08	ABSENCE	ABSENCE	< 1
BRGY. BANLIC							
12/03/2021 10:19	S21-8068	Water Pump, Gran Seville Subdivision	7.65 / 27.3	0.41	ABSENCE	ABSENCE	< 1
12/03/2021 10:29	S21-8069	Gate Entrance, Gran Seville Subdivision	7.55 / 29.0	0.35	ABSENCE	ABSENCE	< 1
BRGY. BIGAA							
12/03/2021 16:36	S21-8106	#253 Elsol Subdivision	7.63 / 27.8	0.79	ABSENCE	ABSENCE	8
BRGY. GULOD							
12/03/2021 15:26	S21-8085	Water Pump, Block 12, Noah St., Celestine Ville	7.67 / 29.1	0.62	ABSENCE	ABSENCE	4
12/03/2021 15:37	S21-8086	Guardhouse, Celestine Ville	7.65 / 27.2	0.45	ABSENCE	ABSENCE	< 1
BRGY. MARINIG							
12/03/2021 15:23	S21-8094	Block 3 Lot 17, Phase 1, Celestine Homes	8.20 / 29.0	0.12	ABSENCE	ABSENCE	< 1
12/03/2021 15:11	S21-8095	Block 23, Lot 10, Phase 1, Celestine Homes	8.14 / 30.5	0.06	ABSENCE	ABSENCE	11
12/03/2021 14:53	S21-8096	Water Pump, Block 9, Carnation St., Phase 2, Celestine Homes	8.14 / 29.9	0.47	ABSENCE	ABSENCE	< 1
12/03/2021 15:02	S21-8097	Block 13 Lot 2, Phase 2, Celestine Homes	8.21 / 29.3	0.35	ABSENCE	ABSENCE	< 1
12/03/2021 14:34	S21-8098	Water Pump, Block 25, Phase 3, Southville	8.14 / 29.1	0.68	ABSENCE	ABSENCE	< 1


NOT VALID WITHOUT QR CODE



REVIEWED BY:


ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
12/03/2021 14:08	S21-8099	Block 19 Lot 33, Phase 3, Southville	8.09 / 28.8	0.63	ABSENCE	ABSENCE	< 1
BRGY. NIUGAN							
12/03/2021 16:19	S21-8107	Block 2 Lot 6, St. Francis Homes VI	7.76 / 28.5	0.13	ABSENCE	ABSENCE	< 1
12/03/2021 13:53	S21-8101	Block 40 Lot 132, Phase 8, Southville	8.05 / 28.3	0.49	ABSENCE	ABSENCE	< 1
12/03/2021 13:42	S21-8100	Water Pump, Block 42, Phase 8, Southville	7.99 / 28.5	0.72	ABSENCE	ABSENCE	6
12/03/2021 13:29	S21-8103	Block 47 Lot 101, Phase 10, Southville	7.46 / 29.9	< 0.02	ABSENCE	ABSENCE	< 1
12/06/2021 09:27	S21-8171	Water Pump, Block 54, Phase 10, Southville	7.53 / 28.7	0.23	ABSENCE	ABSENCE	23
12/03/2021 16:07	S21-8108	Water Pump, Niugan Elementary School	7.78 / 28.4	0.15	ABSENCE	ABSENCE	2
BRGY. SALA							
12/03/2021 15:36	S21-8109	Gate Entrance, Amaia Scapes	7.76 / 28.6	0.89	ABSENCE	ABSENCE	< 1
BRGY. SAN ISIDRO							
12/03/2021 11:31	S21-8072	Block 3 Lot 33, Multiland IV	7.68 / 29.8	0.33	ABSENCE	ABSENCE	< 1
12/03/2021 10:40	S21-8070	Water Pump, San Isidro Heights Subdivision	7.48 / 29.1	0.32	ABSENCE	ABSENCE	< 1
12/03/2021 10:59	S21-8071	Block 3 Lot 1, San Isidro Heights Subdivision	7.50 / 27.5	0.38	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC – Heterotrophic Plate Count; CFU – Colony Forming Units; MDL – Method Detection Limit; LOQ – Limit of Quantification; NA – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: A – Electrometric; B – Colorimetric; C – Enzyme Substrate; D – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:


ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 23

TOTAL PARAMETERS TESTED : 5


ANALYSIS DATE(S) : 12/03/2021 – 12/08/2021

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. MAMATID							
12/06/2021 16:25	S21-8162	Water Pump, Buena Rosario Subdivision	7.68 / 27.3	0.10	ABSENCE	ABSENCE	< 1
12/06/2021 16:38	S21-8163	Block 7 Lot 6, Buena Rosario Subdivision	7.55 / 29.6	0.08	ABSENCE	ABSENCE	< 1
12/03/2021 13:39	S21-8075	Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes	7.50 / 27.6	0.84	ABSENCE	ABSENCE	< 1
12/03/2021 13:18	S21-8077	Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes	7.65 / 29.5	0.65	ABSENCE	ABSENCE	< 1
12/03/2021 15:09	S21-8083	Water Pump, Block 198, Galacia St., Phase 2, Mabuhay City Homes	7.50 / 29.1	0.07	ABSENCE	ABSENCE	< 1
12/03/2021 13:51	S21-8076	Block 95 Lot 57, Guimaras St., Phase 1 Luxury, Mabuhay City Homes	7.48 / 27.6	0.83	ABSENCE	ABSENCE	< 1
12/03/2021 13:29	S21-8078	Block 134 Lot 22, Phase 2, Mabuhay City Homes	7.58 / 27.6	0.25	ABSENCE	ABSENCE	< 1
12/03/2021 15:13	S21-8084	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes	7.60 / 27.5	0.08	ABSENCE	ABSENCE	8
12/03/2021 11:58	S21-8089	Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City Homes	8.12 / 28.4	0.55	ABSENCE	ABSENCE	< 1
12/03/2021 13:00	S21-8073	Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	7.51 / 28.1	0.69	ABSENCE	ABSENCE	5
12/03/2021 13:12	S21-8074	Block 19 Lot 13, Phase 3 Luxury, Mabuhay City Homes	7.60 / 29.1	0.50	ABSENCE	ABSENCE	6
12/03/2021 12:10	S21-8090	Water Pump, Panganig St., Phase 3 Cluster, Mabuhay City Homes	8.62 / 28.7	0.68	ABSENCE	ABSENCE	< 1
12/03/2021 12:20	S21-8091	Block 1 Lot 17, Dizon St., Phase 3, Mabuhay City Homes	8.46 / 28.8	0.62	ABSENCE	ABSENCE	< 1


NOT VALID WITHOUT QR CODE



REVIEWED BY:


ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C) MDL: NA LOQ: NA	RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
12/03/2021 14:13	S21-8079	Water Pump, Phase 1E Mabuhay Executive	7.68 / 29.1	0.23	ABSENCE	ABSENCE	< 1
12/03/2021 14:21	S21-8080	Block 236 Lot 9, Phase 1E Mabuhay Executive	7.59 / 27.5	0.07	ABSENCE	ABSENCE	< 1
12/03/2021 11:20	S21-8092	Water Pump, Phase 6A, Mabuhay City	8.11 / 27.8	0.70	ABSENCE	ABSENCE	< 1
12/03/2021 11:49	S21-8093	Block 58 Lot 1, Phase 6A, Mabuhay City	8.10 / 28.6	0.06	ABSENCE	ABSENCE	< 1
12/03/2021 16:05	S21-8087	9001,Block 252, Mabuhay City Subdivision	7.50 / 27.3	0.40	ABSENCE	ABSENCE	< 1
12/03/2021 16:16	S21-8088	Diaz Residence, Mabuhay City Subdivision	7.51 / 28.7	0.20	ABSENCE	ABSENCE	< 1
BRGY. PULO							
12/03/2021 10:02	S21-8064	Water Pump, Block 12 Lot 22, Cabuyao Central	7.76 / 28.7	0.04	ABSENCE	ABSENCE	6
12/03/2021 10:12	S21-8065	Clubhouse, Narra Avenue, Cabuyao Central	7.64 / 26.7	0.08	ABSENCE	ABSENCE	2
12/03/2021 09:38	S21-8066	Water Pump, Block 11, Willow Park Homes	7.51 / 29.0	0.40	ABSENCE	ABSENCE	< 1
12/03/2021 09:50	S21-8067	Clubhouse, Willow Park Homes	7.48 / 28.6	0.38	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:


ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)