

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I (CHO-1)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 24

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 01/16/2020-01/18/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C) MDL: NA LOQ: NA	RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	COLIFORM ^C		HPC ^D (CFU/mL)
			TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)			
BRGY. BANAY-BANAY							
01/16/2020 11:17	S20-0331	Water Pump, Block 63, Lakeside Nest Subdivision	7.35 / 28.7	0.60	ABSENCE	ABSENCE	< 1
01/16/2020 11:33	S20-0332	Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision	7.32 / 28.0	0.56	ABSENCE	ABSENCE	< 1
BRGY. BANLIC							
01/17/2020 14:43	S20-0370	Water Pump, Gran Seville Subdivision	7.68 / 28.9	0.17	ABSENCE	ABSENCE	-
01/17/2020 14:54	S20-0371	Gate Entrance, Gran Seville Subdivision	7.64 / 29.0	0.17	ABSENCE	ABSENCE	-
BRGY. BIGAA							
01/16/2020 11:00	S20-0333	#253 Elsol Subdivision	7.17 / 28.4	0.49	ABSENCE	ABSENCE	<1
BRGY. GULOD							
01/16/2020 14:48	S20-0349	Block 12, Noah St., Celestine Ville	7.63 / 30.4	0.06	ABSENCE	ABSENCE	< 1
01/16/2020 14:58	S20-0350	Guardhouse, Celestine Ville	7.63 / 30.4	0.08	ABSENCE	ABSENCE	< 1
BRGY. MARINIG							
01/16/2020 14:30	S20-0321	Block 3 Lot 17, Phase 1, Celestine Homes	7.70 / 28.5	0.46	ABSENCE	ABSENCE	< 1
01/16/2020 14:47	S20-0322	Block 23, Lot 10, Phase 1, Celestine Homes	7.65 / 29.0	0.40	ABSENCE	ABSENCE	<1
01/16/2020 15:00	S20-0323	Block 9, Carnation St., Phase 2, Celestine Homes	7.71 / 29.1	1.04	ABSENCE	ABSENCE	<1
01/16/2020 15:12	S20-0324	Block 13 Lot 2, Phase 2, Celestine Homes	7.60 / 28.9	0.95	ABSENCE	ABSENCE	< 1
01/16/2020 12:38	S20-0325	Water Pump, Block 25, Phase 3, Southville	7.25 / 32.5	0.41	ABSENCE	ABSENCE	1
01/16/2020 12:59	S20-0326	Block 19 Lot 33, Phase 3, Southville	7.21 / 32.6	0.37	ABSENCE	ABSENCE	< 1
BRGY. NIUGAN							
01/16/2020 15:32	S20-0334	Block 2 Lot 6, St. Francis Homes 6	7.15 / 27.5	0.27	ABSENCE	ABSENCE	< 1
01/16/2020 13:40	S20-0351	Water Pump, Phase 9, Southville	7.38 / 30.0	0.33	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR STAMP



O
R
I
G



TR20-0255

February 3, 2020 9:05 PM

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ANALYZED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

ANNA KARIA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 8060968

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20						
01/16/2019 13:48	S20-0352	De Guzman Residence, Phase 9, Southville	7.39 / 29.4	0.29	ABSENCE	ABSENCE	< 1
01/16/2019 12:11	S20-0330	Block 47 Lot 101, Phase 10, Southville	7.14 / 28.7	0.60	ABSENCE	ABSENCE	< 1
01/16/2019 12:02	S20-0327	Water Pump, Block 45, Phase 8	7.43 / 28.7	0.52	ABSENCE	ABSENCE	< 1
01/16/2019 12:15	S20-0328	Block 40 Lot 132, Phase 8	7.40 / 27.8	0.50	ABSENCE	ABSENCE	< 1
01/16/2019 12:00	S20-0329	Water Pump, Block 54, Phase 10, Southville	7.40 / 27.8	0.50	ABSENCE	ABSENCE	< 1
BRGY. SALA							
01/16/2019 13:18	S20-0353	Gate Entrance, Amaia Scapes	7.17 / 34.8	0.40	ABSENCE	ABSENCE	< 1
BRGY. SAN ISIDRO							
01/17/2020 16:26	S20-0374	Block 3 Lot 33, Multiland IV	7.58 / 29.2	0.96	ABSENCE	ABSENCE	-
01/17/2020 16:43	S20-0372	Water Pump, San Isidro Heights Subdivision	7.60 / 29.0	0.98	ABSENCE	ABSENCE	-
01/17/2020 16:53	S20-0373	Block 3 Lot 1, San Isidro Heights Subdivision	7.59 / 30.0	1.01	ABSENCE	ABSENCE	-

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR STAMP




O
R
I
G




TR20-0255

February 3, 2020 9:05 PM

ANALYZED BY:


JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II (CHO-2)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 20

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 01/16/2020-01/18/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. MAMATID							
01/16/2020 16:21	S20-0345	Water Pump, Buena Rosario Subdivision	7.70 / 28.9	0.04	ABSENCE	ABSENCE	1
01/16/2020 16:35	S20-0346	Block 8 Lot 6, Buena Rosario Subdivision	7.82 / 28.9	0.07	ABSENCE	ABSENCE	1
01/16/2020 17:27	S20-0339	Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes	7.86 / 28.9	0.72	ABSENCE	ABSENCE	1
01/16/2020 17:41	S20-0340	Block 95 Lot 57, Guimaras St., Phase 1, Mabuhay City Homes	7.84 / 28.6	0.69	ABSENCE	ABSENCE	2
01/16/2020 15:24	S20-0341	Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes	7.92 / 30.8	0.36	ABSENCE	ABSENCE	1
01/16/2020 15:35	S20-0342	Block 134 Lot 22, Phase 2, Mabuhay City Homes	7.66 / 29.1	0.55	ABSENCE	ABSENCE	< 1
01/16/2020 16:03	S20-0347	Water Pump, Block 198, Galacia St., Phase 2, Mabuhay City Homes	7.63 / 29.1	0.59	ABSENCE	ABSENCE	< 1
01/16/2020 15:46	S20-0348	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes	7.71 / 28.9	0.58	ABSENCE	ABSENCE	< 1
01/16/2020 15:24	S20-0341	Water Pump, Block 41, Carmona St., Phase 2, Mabuhay City Homes	7.77 / 29.5	0.22	ABSENCE	ABSENCE	< 1
01/16/2020 15:35	S20-0342	Block 134 Lot 22, Phase 2, Mabuhay City Homes,	7.66 / 29.1	0.55	ABSENCE	ABSENCE	< 1
01/16/2020 14:26	S20-0337	Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	8.04 / 29.2	0.57	ABSENCE	ABSENCE	< 1
01/16/2020 14:12	S20-0338	Block 19 Lot 13, Malang St., Phase 3 Luxury, Mabuhay City Homes	7.87 / 29.4	0.57	ABSENCE	ABSENCE	< 1
01/16/2020 16:03	S20-0347	Water Pump, Block 198, Galacia St. Phase 2, Mabuhay City Homes	7.77 / 30.3	0.53	ABSENCE	ABSENCE	< 1
01/16/2020 15:46	S20-0348	Block 222 Lot 20, Mabuhay Avenue, Phase 2, Mabuhay City Homes	7.66 / 30.1	0.60	ABSENCE	ABSENCE	< 1
01/16/2020 16:50	S20-0343	Water Pump, Phase 1E Mabuhay Executive	7.88 / 30.9	0.50	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR STAMP



Q
R
I
G



TR20-0256

February 3, 2020 9:02 PM

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ANALYZED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
01/16/2020 17:00	S20-0344	Block 236 Lot 9, Phase 1E Mabuhay Executive	7.85 / 28.6 MDL: NA LOQ: NA	0.51 MDL: 0.06 LOQ: 0.20	ABSENCE	ABSENCE	<1
BRGY. PULO							
01/16/2020 14:09	S20-0366	Water Pump, Block 12 Lot 22, Cabuyao Central	7.68 / 28.3	0.42	ABSENCE	ABSENCE	-
01/16/2020 14:26	S20-0367	Clubhouse, Narra Avenue, Cabuyao Central	7.85 / 28.6	4.01	ABSENCE	ABSENCE	-
01/16/2020 13:41	S20-0368	Water Pump, Block 11, Willow Park Homes	7.60 / 29.3	0.77	ABSENCE	ABSENCE	-
01/16/2020 13:50	S20-0369	Clubhouse, Willow Park Homes	7.50 / 30.8	0.80	ABSENCE	ABSENCE	-

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR STAMP



Q
R
I
G



TR20-0256


February 3, 2020 9:02 PM

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ANALYZED BY:


JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968