

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II (CHO-2)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 20

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 03/05/2020-03/18/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. MAMATID							
03/05/2020 14:30	S20-1526	Water Pump, Buena Rosario Subdivision	7.69 / 28.9	0.17	ABSENCE	ABSENCE	-
03/05/2020 14:37	S20-1527	Block 7 Lot 6, Buena Rosario Subdivision	7.59 / 27.9	0.14	ABSENCE	ABSENCE	-
03/05/2020 12:00	S20-1520	Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes	7.60 / 28.2	0.80	ABSENCE	ABSENCE	-
03/05/2020 12:10	S20-1521	Block 95 Lot 57, Guimaras St., Phase 1, Mabuhay City Homes	7.55 / 27.9	0.78	ABSENCE	ABSENCE	-
03/05/2020 11:30	S20-1522	Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes	7.96 / 28.8	0.60	ABSENCE	ABSENCE	-
03/05/2020 11:40	S20-1523	Block 134 Lot 22, Phase 2, Mabuhay City Homes	7.20 / 25.5	0.60	ABSENCE	ABSENCE	-
03/05/2020 11:10	S20-1528	Water Pump, Block 198, Galacia St., Phase 2, Mabuhay City Homes	7.58 / 27.6	0.56	ABSENCE	ABSENCE	-
03/05/2020 11:17	S20-1529	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes	7.28 / 27.8	0.56	ABSENCE	ABSENCE	-
03/16/2020 10:39	S20-1868	Water Pump, Joshua St., Phase 5, Mabuhay City Homes	7.70 / 29.5	0.22	ABSENCE	ABSENCE	4
03/16/2020 10:59	S20-1869	Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City Homes	7.69 / 30.1	0.42	ABSENCE	ABSENCE	< 1
03/05/2020 13:10	S20-1518	Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	7.61 / 28.8	0.60	ABSENCE	ABSENCE	1
03/05/2020 13:15	S20-1519	Block 19 Lot 13, Malang St., Phase 3 Luxury, Mabuhay City Homes	7.59 / 27.7	0.55	ABSENCE	ABSENCE	-
03/16/2020 10:04	S20-1870	Water Pump, Panganig St., Phase 3, Mabuhay City Homes	7.75 / 27.9	0.36	ABSENCE	ABSENCE	< 1
03/16/2020 10:16	S20-1871	Block 1 Lot 17, Dizon St., Phase 3, Mabuhay City Homes	7.74 / 28.0	0.30	ABSENCE	ABSENCE	< 1
03/05/2020 14:10	S20-1524	Water Pump, Phase 1E Mabuhay Executive	7.35 / 35.3	0.60	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR STAMP



QR
I
G



TR20-0825

March 24, 2020 3:05 PM

REVIEWED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
03/05/2020 14:15	S20-1525	Block 236 Lot 9, Phase 1E Mabuhay Executive	7.30 / 30.1	0.58	ABSENCE	ABSENCE	-
BRGY. PULO							
03/16/2020 12:30	S20-1859	Water Pump, Block 12 Lot 22, Cabuyao Central	7.23 / 27.3	0.07	ABSENCE	ABSENCE	1
03/16/2020 12:44	S20-1860	Clubhouse, Narra Avenue, Cabuyao Central	7.78 / 28.3	0.04	ABSENCE	ABSENCE	< 1
03/16/2020 13:05	S20-1861	Water Pump, Block 11, Willow Park Homes	7.37 / 27.9	0.45	ABSENCE	ABSENCE	< 1
03/16/2020 13:15	S20-1862	Clubhouse, Willow Park Homes	7.31 / 27.6	0.36	ABSENCE	ABSENCE	2

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR STAMP




O
R
I
G




TR20-0825

March 24, 2020 3:05 PM

REVIEWED BY:


JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I (CHO-1)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 24

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 03/05/2020-03/18/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. BANAY-BANAY							
03/13/2020 13:32	S20-1819	Water Pump, Block 63, Lakeside Nest Subdivision	7.77 / 29.5	0.32	ABSENCE	ABSENCE	1
03/13/2020 13:49	S20-1820	Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision	7.46 / 38.9	0.50	ABSENCE	ABSENCE	< 1
BRGY. BANLIC							
03/16/2020 11:52	S20-1863	Water Pump, Gran Seville Subdivision	7.31 / 27.6	0.36	ABSENCE	ABSENCE	< 1
03/16/2020 12:02	S20-1864	Gate Entrance, Gran Seville Subdivision	7.63 / 27.6	0.23	ABSENCE	ABSENCE	4
BRGY. BIGAA							
03/13/2020 10:44	S20-1821	#253 Elsol Subdivision	7.78 / 30.1	0.55	ABSENCE	ABSENCE	<1
BRGY. GULOD							
03/05/2020 13:40	S20-1530	Block 12, Noah St., Celestine Ville	7.53 / 29.6	0.14	ABSENCE	ABSENCE	-
03/05/2020 13:57	S20-1531	Guardhouse, Celestine Ville	7.49 / 28.9	0.09	ABSENCE	ABSENCE	-
BRGY. MARINIG							
03/13/2020 11:10	S20-1809	Block 3 Lot 17, Phase 1, Celestine Homes	7.94 / 30.1	0.71	ABSENCE	ABSENCE	< 1
03/13/2020 12:01	S20-1810	Block 23, Lot 10, Phase 1, Celestine Homes	8.01 / 32.3	0.39	ABSENCE	ABSENCE	<1
03/13/2020 11:43	S20-1811	Block 9, Carnation St., Phase 2, Celestine Homes	7.97 / 30.2	1.17	ABSENCE	ABSENCE	<1
03/13/2020 11:49	S20-1812	Block 13 Lot 2, Phase 2, Celestine Homes	7.93 / 30.3	1.11	ABSENCE	ABSENCE	< 1
03/13/2020 12:20	S20-1813	Water Pump, Block 25, Phase 3, Southville	7.90 / 32.5	0.06	ABSENCE	ABSENCE	6
03/13/2020 12:20	S20-1814	Block 19 Lot 33, Phase 3, Southville	8.11 / 30.1	0.08	ABSENCE	ABSENCE	< 1
BRGY. NIUGAN							
03/13/2020 12:45	S20-1816	Block 2 Lot 6, St. Francis Homes 6	7.15 / 27.5	0.27	ABSENCE	ABSENCE	< 1
03/05/2020 15:00	S20-1532	Water Pump, Phase 9, Southville	7.36 / 34.0	0.80	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR STAMP

ANALYZED BY:

CERTIFIED CORRECT BY:



O
R
I
G



TR20-0824

March 24, 2020 3:04 PM

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060958

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
03/05/2020 15:15	S20-1533	De Guzman Residence, Phase 9, Southville	7.25 / 27.5	0.55	ABSENCE	ABSENCE	-
03/13/2020 13:17	S20-1818	Block 47 Lot 101, Phase 10, Southville	7.79 / 32.2	0.32	ABSENCE	ABSENCE	1
03/13/2020 12:56	S20-1815	Water Pump, Block 45, Phase 8	7.90 / 29.6	0.38	ABSENCE	ABSENCE	< 1
03/13/2020 12:45	S20-1816	Block 40 Lot 129, Phase 8	8.06 / 29.7	0.42	ABSENCE	ABSENCE	1
03/13/2020 13:11	S20-1817	Water Pump, Block 54, Phase 10, Southville	7.84 / 28.9	0.47	ABSENCE	ABSENCE	3
BRGY. SALA							
03/05/2020 15:15	S20-1534	Gate Entrance, Amaia Scapes	7.25 / 27.5	0.55	ABSENCE	ABSENCE	-
BRGY. SAN ISIDRO							
03/16/2020 11:24	S20-1867	Block 3 Lot 33, Multiland IV	7.64 / 28.1	0.48	ABSENCE	ABSENCE	5
03/16/2020 11:10	S20-1865	Water Pump, San Isidro Heights Subdivision	7.64 / 27.3	0.78	ABSENCE	ABSENCE	6
03/16/2020 11:18	S20-1866	Block 3 Lot 1, San Isidro Heights Subdivision	7.68 / 27.6	0.72	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric ; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR STAMP



TR20-0824

March 24, 2020 3:04 PM

O
R
I
G



ANALYZED BY:

Jethro D. Escobin
JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

Anna Karla S. Gutierrez
ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060958

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis