

DOH Accredited Testing Laboratory (4A-0005-2426-LW-2)
PNRI (RML No. Y04.04132.23)
PRC Certificate of Authority to Operate No. 111
PNP (License No. PDD03-230616-04201)
DENR Environmental Laboratory Recognition (C.R. No.091/2022)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916 **WEBSITE:** www.lagunawater.com.ph

CUSTOMER NAME: LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 14 TOTAL PARAMETERS TESTED : 3

ANALYSIS DATE(S) : 08/06/2024-08/27/2024

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER		
			COLIFORM ^A		
			TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^B (CFU/mL)
BRGY. BIGAA					
08/06/2024 09:30	S24-4378	#253 Elsol Subdivision	ABSENCE	ABSENCE	< 1
BRGY. GULOD					
08/12/2024 14:55	S24-4504	Guard House, Celestine Ville	ABSENCE	ABSENCE	< 1
BRGY. MARINIG					
08/06/2024 10:12	S24-4361	Celestine Homes, Phase 1 Subdivision	ABSENCE	ABSENCE	< 1
08/06/2024 11:04	S24-4362	Block 23, Lot 10, Phase 1, Celestine Homes	ABSENCE	ABSENCE	< 1
08/06/2024 10:39	S24-4364	Celestine Homes, Phase 2 Subdivision	ABSENCE	ABSENCE	< 1
08/06/2024 10:52	S24-4365	Block 13 Lot 2, Phase 2, Celestine Homes	ABSENCE	ABSENCE	< 1
08/06/2024 11:39	S24-4367	Water Pump, Block 25, Phase 3, Southville	ABSENCE	ABSENCE	< 1
08/06/2024 11:54	S24-4368	Block 19 Lot 33, Phase 3, Southville	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE

REVIEWED BY:

NOWEL ELLISON G. RAMOS, RMT Microbiology Unit Manager License No(s). (PRC 0090336) **CERTIFIED CORRECT BY:**

ANNA KARLA & GUTTERREZ, RMT Laboratory Services Manager License No(s). (PRC 0060968)



DOH Accredited Testing Laboratory (4A-0005-2426-LW-2)
PNRI (RML No. Y04.04132.23)
PRC Certificate of Authority to Operate No. 111
PNP (License No. PDD03-230616-04201)
DENR Environmental Laboratory Recognition (C.R. No.091/2022)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER			
			COLIFORM ^A			
			TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^B (CFU/mL)	
BRGY. NIUGAN			•			
08/06/2024 09:11	S24-4379	Block 2 Lot 6, St. Francis Homes VI	ABSENCE	ABSENCE	440	
08/06/2024 12:42	S24-4371	Block 40 Lot 132, Phase 8, Southville	ABSENCE	ABSENCE	<1	
08/06/2024 13:22	S24-4370	Water Pump, Block 42, Phase 8, Southville	ABSENCE	ABSENCE	<1	
08/06/2024 14:13	S24-4374	Block 47 Lot 101, Phase 10, Southville	ABSENCE	ABSENCE	<1	
08/06/2024 14:04	S24-4373	Water Pump, Block 54, Phase 10, Southville	ABSENCE	ABSENCE	<1	
BRGY. SALA	<u>. </u>		•			
08/06/2024 09:52	S24-4380	Gate Entrance, Amaia Scapes	ABSENCE	ABSENCE	220	

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: <u>HPC</u> – Heterotrophic Plate Count; <u>CFU</u> – Colony Forming Units; <u>MDL</u> – Method Detection Limit; <u>LOQ</u> – Limit of Quantification; <u>NA</u> – Not Applicable; (-) Not performed

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: A- Enzyme Substrate; B - Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE

REVIEWED BY:

NOWEL ELLISON G. RAMOS, RMT Microbiology Unit Manager License No(s). (PRC 0090336) **CERTIFIED CORRECT BY:**

ANNA KARLA & GUTTERREZ, RMT Laboratory Services Manager License No(s). (PRC 0060968)



DOH Accredited Testing Laboratory (4A-0005-2426-LW-2)
PNRI (RML No. Y04.04132.23)
PRC Certificate of Authority to Operate No. 111
PNP (License No. PDD03-230616-04201)
DENR Environmental Laboratory Recognition (C.R. No.091/2022)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME: LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 31 TOTAL PARAMETERS TESTED : 3

ANALYSIS DATE(S) : 08/06/2024-08/27/2024

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER		
			COLIFORM ^A		
			TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^B (CFU/mL)
BRGY. BANAY-BANAY					
08/06/2024 14:35	S24-4376	Water Pump, Block 63, Lakeside Nest Subdivision	ABSENCE	ABSENCE	< 1
08/06/2024 15:03	S24-4377	Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision	ABSENCE	ABSENCE	< 1
BRGY. BANLIC					
08/19/2024 09:51	S24-4664	Water Pump, Gran Seville Subdivision	ABSENCE	ABSENCE	< 1
08/19/2024 10:10	S24-4665	Gate Entrance, Gran Seville Subdivision	ABSENCE	ABSENCE	< 1
BRGY. MAMATID					
08/12/2024 14:19	S24-4499	Water Pump, Buena Rosario Subdivision	ABSENCE	ABSENCE	< 1
08/12/2024 14:35	S24-4500	Block 7 Lot 6, Buena Rosario Subdivision	ABSENCE	ABSENCE	< 1
08/12/2024 11:36	S24-4493	Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes	ABSENCE	ABSENCE	<1
08/12/2024 12:43	S24-4490	Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes	ABSENCE	ABSENCE	<1
08/12/2024 12:57	S24-4491	Block 95 Lot 57, Guimaras St., Phase 1 Luxury, Mabuhay City Homes	ABSENCE	ABSENCE	<1
08/12/2024 11:47	S24-4494	Block 134 Lot 22, Phase 2, Mabuhay City Homes	ABSENCE	ABSENCE	< 1
08/12/2024 10:58	S24-4503	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes	ABSENCE	ABSENCE	<1
08/12/2024 10:50	S24-4502	Water Pump, Block 198, Galacia St., Phase II	ABSENCE	ABSENCE	< 1
08/06/2024 15:59	S24-4385	Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City Homes	ABSENCE	ABSENCE	<1
08/12/2024 09:48	S24-4487	Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	ABSENCE	ABSENCE	<1
08/12/2024 09:59	S24-4488	Block 19 Lot 13, Phase 3 Luxury, Mabuhay City Homes	ABSENCE	ABSENCE	< 1
08/06/2024 15:36	S24-4387	Water Pump, Panganig St., Phase 3 Cluster, Mabuhay City Homes	ABSENCE	ABSENCE	<1

NOT VALID WITHOUT QR CODE

REVIEWED BY:

CERTIFIED CORRECT BY:

NOWEL ELLISON G. RAMOS, RMT Microbiology Unit Manager License No(s). (PRC 0090336) ANNA KARLA S. GUTTERREZ, RMT Laboratory Services Manager License No(s). (PRC 0060968)



DOH Accredited Testing Laboratory (4A-0005-2426-LW-2)
PNRI (RML No. Y04.04132.23)
PRC Certificate of Authority to Operate No. 111
PNP (License No. PDD03-230616-04201)
DENR Environmental Laboratory Recognition (C.R. No.091/2022)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916 **WEBSITE:** www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER			
			COLIFORMA			
			TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^B (CFU/mL)	
08/06/2024 15:48	S24-4388	Block 1 Lot 17, Dizon St., Phase 3, Mabuhay City Homes	ABSENCE	ABSENCE	<1	
08/12/2024 13:29	S24-4496	Water Pump, Phase 1E Mabuhay Executive	ABSENCE	ABSENCE	<1	
08/12/2024 13:40	S24-4497	Block 236 Lot 9, Phase 1E Mabuhay Executive	ABSENCE	ABSENCE	<1	
08/06/2024 16:21	S24-4390	Water Pump, Phase 6A, Mabuhay City	ABSENCE	ABSENCE	<1	
08/06/2024 16:33	S24-4391	Block 58 Lot 6, Phase 6A, Mabuhay City	ABSENCE	ABSENCE	<1	
08/12/2024 14:55	S24-4505	9001, Block 252, Mabuhay City Subdivision	ABSENCE	ABSENCE	<1	
08/12/2024 15:10	S24-4506	Jimeno Residence, Mabuhay City Subdivision	ABSENCE	ABSENCE	<1	
BRGY. PULO						
08/19/2024 12:10	S24-4658	Water Pump, Block 12 Lot 22, Cabuyao Central	ABSENCE	ABSENCE	<1	
08/19/2024 12:19	S24-4659	Clubhouse, Narra Avenue, Cabuyao Central	ABSENCE	ABSENCE	4	
08/19/2024 11:16	\$24-4661	Water Pump, Block 11, Willow Park Homes	ABSENCE	ABSENCE	3	
08/19/2024 11:21	S24-4662	Clubhouse, Willow Park Homes	ABSENCE	ABSENCE	3	
BRGY. SAN ISIDRO						
08/06/2024 16:48	S24-4392	Block 3 Lot 14B, Multiland IV	ABSENCE	ABSENCE	<1	
08/19/2024 10:21	S24-4667	Water Pump, San Isidro Homes Subdivision	ABSENCE	ABSENCE	<1	
08/19/2024 10:44	S24-4668	Block 3 Lot 1, San Isidro Heights Subdivision	ABSENCE	ABSENCE	<1	

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: <u>HPC</u> – Heterotrophic Plate Count; <u>CFU</u> – Colony Forming Units; <u>MDL</u> – Method Detection Limit; <u>LOQ</u> – Limit of Quantification; <u>NA</u> – Not Applicable (-) Not performed

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: A- Enzyme Substrate; B - Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE

REVIEWED BY:

NOWEL ELLISON G. RAMOS, RMT Microbiology Unit Manager License No(s). (PRC 0090336) **CERTIFIED CORRECT BY:**

ANNA KARLA (S) GUTIERREZ, RMT Laboratory Services Manager License No(s). (PRC 0060968)