

DOH Accredited Testing Laboratory (4A-0005-2426-LW-2)
PNRI (RML No. Y04.04132.23)
PRC Certificate of Authority to Operate No. 111
PNP (License No. PDD03-230616-04201)
DENR Environmental Laboratory Recognition (C.R. No.091/2022)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916 **WEBSITE:** www.lagunawater.com.ph

CUSTOMER NAME: LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 15 TOTAL PARAMETERS TESTED : 3

ANALYSIS DATE(S) : 07/01/2024-07/30/2024

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER		
			COLIFORM ^A		
			TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^B (CFU/mL)
BRGY. BIGAA					
07/01/2024 10:30	S24-3701	#253 Elsol Subdivision	ABSENCE	ABSENCE	< 1
BRGY. GULOD					
07/01/2024 12:50	S24-3667	Celestine Ville Subdivision	ABSENCE	ABSENCE	< 1
07/01/2024 13:10	S24-3668	Guard House, Celestine Ville	ABSENCE	ABSENCE	< 1
BRGY. MARINIG					
07/01/2024 12:34	S24-3684	Celestine Homes, Phase 1 Subdivision	ABSENCE	ABSENCE	< 1
07/01/2024 12:24	S24-3685	Block 23, Lot 10, Phase 1, Celestine Homes	ABSENCE	ABSENCE	< 1
07/01/2024 11:50	S24-3687	Celestine Homes, Phase 2 Subdivision	ABSENCE	ABSENCE	<1
07/01/2024 12:06	S24-3688	Block 13 Lot 2, Phase 2, Celestine Homes	ABSENCE	ABSENCE	19
07/25/2024 14:21	S24-4243	Water Pump, Block 25, Phase 3, Southville	ABSENCE	ABSENCE	<1
07/25/2024 14:36	S24-4244	Block 19 Lot 33, Phase 3, Southville	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE

REVIEWED BY:

CERTIFIED CORRECT BY:

NOWEL ELLISON G. RAMOS, RMT Microbiology Unit Manager License No(s). (PRC 0090336) ANNA KARLÀ & GUTTERREZ, RMT Laboratory Services Manager License No(s). (PRC 0060968)



DOH Accredited Testing Laboratory (4A-0005-2426-LW-2)
PNRI (RML No. Y04.04132.23)
PRC Certificate of Authority to Operate No. 111
PNP (License No. PDD03-230616-04201)
DENR Environmental Laboratory Recognition (C.R. No.091/2022)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED		SAMPLE LOCATION	PARAMETER		
			COLIFORM ^A		
	SAMPLE CODE		TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^B (CFU/mL)
BRGY. NIUGAN					
07/25/2024 14:04	S24-4245	Block 2 Lot 6, St. Francis Homes VI	ABSENCE	ABSENCE	<1
07/01/2024 13:36	S24-3694	Block 40 Lot 132, Phase 8, Southville	ABSENCE	ABSENCE	<1
07/01/2024 13:42	S24-3693	Water Pump, Block 42, Phase 8, Southville	ABSENCE	ABSENCE	62
07/01/2024 14:27	S24-3697	Block 47 Lot 101, Phase 10, Southville	ABSENCE	ABSENCE	4
07/01/2024 14:28	S24-3696	Water Pump, Block 54, Phase 10, Southville	ABSENCE	ABSENCE	<1
BRGY. SALA					
07/01/2024 11:03	S24-3703	Gate Entrance, Amaia Scapes	ABSENCE	ABSENCE	18

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: <u>HPC</u> – Heterotrophic Plate Count; <u>CFU</u> – Colony Forming Units; <u>MDL</u> – Method Detection Limit; <u>LOQ</u> – Limit of Quantification; <u>NA</u> – Not Applicable; (-) Not

performed

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: A- Enzyme Substrate; B – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE

REVIEWED BY:

CERTIFIED CORRECT BY:

NOWEL ELLISON G. RAMOS, RMT Microbiology Unit Manager License No(s). (PRC 0090336) ANNA KARLA & GUTTERREZ, RMT Laboratory Services Manager License No(s). (PRC 0060968)



DOH Accredited Testing Laboratory (4A-0005-2426-LW-2)
PNRI (RML No. Y04.04132.23)
PRC Certificate of Authority to Operate No. 111
PNP (License No. PDD03-230616-04201)
DENR Environmental Laboratory Recognition (C.R. No.091/2022)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME: LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 31 TOTAL PARAMETERS TESTED : 3

ANALYSIS DATE(S) : 07/01/2024-07/30/2024

DATE/TIME COLLECTED		SAMPLE LOCATION	PARAMETER		
	SAMPLE CODE		COLIFORM ^A		
			TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^B (CFU/mL)
BRGY. BANAY-BANAY					
07/01/2024 14:39	S24-3699	Water Pump, Block 63, Lakeside Nest Subdivision	ABSENCE	ABSENCE	36
07/01/2024 14:51	S24-3700	Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision	ABSENCE	ABSENCE	98
BRGY. BANLIC					
07/01/2024 08:21	S24-3678	Water Pump, Gran Seville Subdivision	ABSENCE	ABSENCE	< 1
07/01/2024 08:38	S24-3679	Gate Entrance, Gran Seville Subdivision	ABSENCE	ABSENCE	< 1
BRGY. MAMATID					
07/01/2024 15:06	S24-3661	Water Pump, Buena Rosario Subdivision	ABSENCE	ABSENCE	< 1
07/01/2024 15:14	S24-3662	Block 7 Lot 6, Buena Rosario Subdivision	ABSENCE	ABSENCE	< 1
07/01/2024 12:21	S24-3655	Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes	ABSENCE	ABSENCE	<1
07/01/2024 13:17	S24-3652	Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes	ABSENCE	ABSENCE	<1
07/01/2024 14:10	S24-3653	Block 95 Lot 57, Guimaras St., Phase 1 Luxury, Mabuhay City Homes	ABSENCE	ABSENCE	<1
07/01/2024 12:46	S24-3656	Block 134 Lot 22, Phase 2, Mabuhay City Homes	ABSENCE	ABSENCE	< 1
07/01/2024 11:46	\$24-3665	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes	ABSENCE	ABSENCE	<1
07/01/2024 11:36	S24-3664	Water Pump, Block 198, Galacia St., Phase II	ABSENCE	ABSENCE	< 1
07/01/2024 15:57	S24-3708	Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City Homes	ABSENCE	ABSENCE	220
07/01/2024 13:21	S24-3649	Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	ABSENCE	ABSENCE	< 1
07/01/2024 13:33	S24-3650	Block 19 Lot 13, Phase 3 Luxury, Mabuhay City Homes	ABSENCE	ABSENCE	< 1
07/01/2024 15:24	S24-3710	Water Pump, Panganig St., Phase 3 Cluster, Mabuhay City Homes	ABSENCE	ABSENCE	2

NOT VALID WITHOUT QR CODE

REVIEWED BY:

CERTIFIED CORRECT BY:

NOWEL ELLISON G. RAMOS, RMT Microbiology Unit Manager License No(s). (PRC 0090336) ANNA KARLAS. GOTHERREZ, RMT Laboratory Services Manager License No(s). (PRC 0060968)



DOH Accredited Testing Laboratory (4A-0005-2426-LW-2)
PNRI (RML No. Y04.04132.23)
PRC Certificate of Authority to Operate No. 111
PNP (License No. PDD03-230616-04201)
DENR Environmental Laboratory Recognition (C.R. No.091/2022)

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916 **WEBSITE:** www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER		
			COLIFORMA		
			TOTAL (Coliforms/ 100mL)	FECAL/ E. coli (Coliforms/ 100 mL)	HPC ^B (CFU/mL)
07/01/2024 15:36	S24-3711	Block 1 Lot 17, Dizon St., Phase 3, Mabuhay City Homes	ABSENCE	ABSENCE	< 1
07/01/2024 14:31	\$24-3658	Water Pump, Phase 1E Mabuhay Executive	ABSENCE	ABSENCE	< 1
07/01/2024 14:40	S24-3659	Block 236 Lot 9, Phase 1E Mabuhay Executive	ABSENCE	ABSENCE	< 1
07/01/2024 16:07	S24-3713	Water Pump, Phase 6A, Mabuhay City	ABSENCE	ABSENCE	< 1
07/01/2024 16:18	S24-3714	Block 58 Lot 6, Phase 6A, Mabuhay City	ABSENCE	ABSENCE	< 1
07/01/2024 15:20	S24-3669	9001, Block 252, Mabuhay City Subdivision	ABSENCE	ABSENCE	< 1
07/01/2024 15:34	S24-3670	Jimeno Residence, Mabuhay City Subdivision	ABSENCE	ABSENCE	< 1
BRGY. PULO					
07/01/2024 10:29	S24-3672	Water Pump, Block 12 Lot 22, Cabuyao Central	ABSENCE	ABSENCE	2
07/01/2024 10:43	S24-3673	Clubhouse, Narra Avenue, Cabuyao Central	ABSENCE	ABSENCE	< 1
07/01/2024 09:46	S24-3675	Water Pump, Block 11, Willow Park Homes	ABSENCE	ABSENCE	< 1
07/01/2024 09:55	S24-3676	Clubhouse, Willow Park Homes	ABSENCE	ABSENCE	<1
BRGY. SAN ISIDRO					
07/01/2024 16:41	S24-3715	Block 3 Lot 14B, Multiland IV	ABSENCE	ABSENCE	110
07/01/2024 09:01	S24-3681	Water Pump, San Isidro Homes Subdivision	ABSENCE	ABSENCE	<1
07/01/2024 09:20	S24-3682	Block 3 Lot 1, San Isidro Heights Subdivision	ABSENCE	ABSENCE	<1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: <u>HPC</u> – Heterotrophic Plate Count; <u>CFU</u> – Colony Forming Units; <u>MDL</u> – Method Detection Limit; <u>LOQ</u> – Limit of Quantification; <u>NA</u> – Not Applicable (-) Not performed

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: A- Enzyme Substrate; B - Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE

REVIEWED BY:

NOWEL ELLISON G. RAMOS, RMT Microbiology Unit Manager License No(s). (PRC 0090336) **CERTIFIED CORRECT BY:**

ANNA KARLA () GUTIERREZ, RMT Laboratory Services Manager License No(s). (PRC 0060968)