

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE I

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 22

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 01/06/2021-1/27/2021

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. BANAY-BANAY							
01/06/2021 09:58	S21-0102	Water Pump, Block 63, Lakeside Nest Subdivision	7.57 / 31.2	0.30	ABSENCE	ABSENCE	< 1
01/06/2021 10:04	S21-0103	Block 12, Lot 5, Phase 4, Lakeside Nest Subdivision	7.37 / 29.6	0.22	ABSENCE	ABSENCE	< 1
BRGY. BANLIC							
01/06/2021 11:12	S21-0068	Water Pump, Gran Seville Subdivision	-	0.26	ABSENCE	ABSENCE	< 1
01/06/2021 11:36	S21-0069	Gate Entrance, Gran Seville Subdivision	-	0.17	ABSENCE	ABSENCE	1
BRGY. BIGAA							
01/06/2021 09:15	S21-0104	#253 Elsol Subdivision	7.47 / 30.5	0.33	ABSENCE	ABSENCE	< 1
BRGY. GULOD							
01/06/2021 12:15	S21-0089	Water Pump, Block 12, Noah St., Celestine Ville	7.51 / 27.6	0.28	ABSENCE	ABSENCE	1
01/06/2021 12:30	S21-0090	Guardhouse, Celestine Ville	7.48 / 27.4	0.21	ABSENCE	ABSENCE	< 1
BRGY. MARINIG							
01/06/2021 10:11	S21-0092	Block 3 Lot 17, Phase 1, Celestine Homes	7.44 / 29.6	0.32	ABSENCE	ABSENCE	< 1
01/06/2021 10:24	S21-0093	Block 23, Lot 10, Phase 1, Celestine Homes	7.47 / 29.6	0.28	ABSENCE	ABSENCE	< 1
01/06/2021 10:52	S21-0094	Water Pump, Block 9, Carnation St., Phase 2, Celestine Homes	7.52 / 28.7	0.35	ABSENCE	ABSENCE	2
01/06/2021 11:07	S21-0095	Block 13 Lot 2, Phase 2, Celestine Homes	7.45 / 29.7	0.30	ABSENCE	ABSENCE	< 1
01/06/2021 11:30	S21-0096	Water Pump, Block 25, Phase 3, Southville	7.60 / 29.6	0.40	ABSENCE	ABSENCE	< 1
01/06/2021 11:44	S21-0097	Block 19 Lot 33, Phase 3, Southville	7.92 / 28.6	0.32	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. NIUGAN							
01/06/2021 09:37	S21-0105	Block 2 Lot 6, St. Francis Homes	7.35 / 29.3	0.22	ABSENCE	ABSENCE	< 1
01/06/2021 12:27	S21-0099	Block 40 Lot 132, Phase 8, Southville	7.44 / 29.7	0.28	ABSENCE	ABSENCE	< 1
01/06/2021 12:09	S21-0098	Water Pump, Block 45, Phase 8, Southville	7.57 / 27.6	0.44	ABSENCE	ABSENCE	1
01/06/2021 13:58	S21-0101	Block 47 Lot 101, Phase 10, Southville	7.60 / 30.4	0.08	ABSENCE	ABSENCE	1
01/06/2021 13:20	S21-0100	Water Pump, Block 54, Phase 10, Southville	7.39 / 29.8	0.12	ABSENCE	ABSENCE	1
BRGY. SALA							
01/06/2021 13:34	S21-0091	Guard House, Amaia Scapes	7.58 / 27.5	0.65	ABSENCE	ABSENCE	1
BRGY. SAN ISIDRO							
01/06/2021 11:52	S21-0072	Block 3 Lot 33, Multiland IV	-	0.09	ABSENCE	ABSENCE	< 1
01/06/2021 12:07	S21-0070	Water Pump, San Isidro Heights Subdivision	-	0.95	ABSENCE	ABSENCE	< 1
01/06/2021 12:16	S21-0071	Block 3 Lot 1, San Isidro Heights Subdivision	-	0.71	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC – Heterotrophic Plate Count; CFU – Colony Forming Units; MDL – Method Detection Limit; LOQ – Limit of Quantification; NA – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: A – Electrometric; B – Colorimetric; C – Enzyme Substrate; D – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:


ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : CABUYAO CITY HEALTH OFFICE II (CHO-2)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 20

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 01/06/2021-1/08/2021

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. MAMATID							
01/06/2021 11:05	S21-0085	Water Pump, Buena Rosario Subdivision	7.57 / 29.5	0.06	ABSENCE	ABSENCE	< 1
01/06/2021 11:20	S21-0086	Block 7 Lot 6, Buena Rosario Subdivision	7.49 / 29.6	0.04	ABSENCE	ABSENCE	< 1
01/06/2021 09:26	S21-0079	Water Pump, Block 101, Samar St., Phase 2, Mabuhay City Homes	7.55 / 29.5	0.38	ABSENCE	ABSENCE	< 1
01/06/2021 09:50	S21-0081	Water Pump, Block 141, Carmona St., Phase 2, Mabuhay City Homes	7.56 / 27.5	0.48	ABSENCE	ABSENCE	< 1
01/06/2021 11:38	S21-0087	Water Pump, Block 198, Galacia St., Phase 2, Mabuhay City Homes	7.45 / 27.6	0.51	ABSENCE	ABSENCE	< 1
01/06/2021 09:37	S21-0080	Block 95 Lot 57, Guimaras St., Phase 1 Luxury, Mabuhay City Homes	7.60 / 28.6	0.25	ABSENCE	ABSENCE	< 1
01/06/2021 09:59	S21-0082	Block 134 Lot 22, Phase 2, Mabuhay City Homes	7.58 / 27.5	0.36	ABSENCE	ABSENCE	< 1
01/06/2021 12:00	S21-0088	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay City Homes	7.46 / 27.8	0.43	ABSENCE	ABSENCE	10
01/06/2021 12:19	S21-0073	Water Pump, Joshua St., Phase 5, Mabuhay City Homes	-	0.96	ABSENCE	ABSENCE	< 1
01/06/2021 12:32	S21-0074	Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City Homes	-	0.49	ABSENCE	ABSENCE	290
01/06/2021 09:00	S21-0077	Water Pump, Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	7.15 / 27.6	0.70	ABSENCE	ABSENCE	< 1
01/06/2021 09:11	S21-0078	Block 19 Lot 13, Phase 3 Luxury, Mabuhay City Homes	7.50 / 28.6	0.65	ABSENCE	ABSENCE	< 1
01/06/2021 12:53	S21-0075	Water Pump, Panganig St., Phase 3, Mabuhay City Homes	-	0.46	ABSENCE	ABSENCE	5
01/06/2021 12:44	S21-0076	Block 1 Lot 17, Dizon St., Phase 3, Mabuhay City Homes	-	0.55	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
01/06/2021 10:20	S21-0083	Water Pump, Phase 1E Mabuhay Executive	7.61 / 29.9	0.16	ABSENCE	ABSENCE	< 1
01/06/2021 10:34	S21-0084	Block 236 Lot 9, Phase 1E Mabuhay Executive	7.55 / 28.6	0.11	ABSENCE	ABSENCE	< 1
BRGY. PULO							
01/06/2021 10:50	S21-0064	Water Pump, Block 12 Lot 22, Cabuyao Central	-	0.38	ABSENCE	ABSENCE	2
01/06/2021 10:59	S21-0065	Clubhouse, Narra Avenue, Cabuyao Central	-	0.27	ABSENCE	ABSENCE	< 1
01/06/2021 10:28	S21-0066	Water Pump, Block 11, Willow Park Homes	-	0.24	ABSENCE	ABSENCE	< 1
01/06/2021 10:35	S21-0067	Clubhouse, Willow Park Homes	-	0.25	ABSENCE	ABSENCE	2

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:


ALYSSA MARIE C. PINALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis