

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE I

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 22

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 05/03/2021 – 05/21/2021

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. BIÑAN							
05/03/2021 16:00	S21-3223	Laguna Wellfield 1	7.51 / 27.8	0.67	ABSENCE	ABSENCE	< 1
BRGY. CAINGIN							
05/19/2021 12:25	S21-3783	Water Pump, Block 57, Phase 1, Southville	-	1.28	ABSENCE	ABSENCE	< 1
05/19/2021 12:44	S21-3784	Block 25 Lot 7, Phase 3, Southville	-	1.08	ABSENCE	ABSENCE	< 1
05/19/2021 12:32	S21-3785	Block 52 Lot 27, Southville	-	1.33	ABSENCE	ABSENCE	< 1
05/19/2021 12:01	S21-3786	Block 2 Lot 16, Phase 9, Southville	-	0.20	ABSENCE	ABSENCE	< 1
BRGY. KANLURAN							
05/19/2021 13:15	S21-3780	Gate Entrance, Alfonso Homes I	-	0.43	ABSENCE	ABSENCE	< 1
05/19/2021 13:23	S21-3778	#621 Rizal Boulevard	-	0.40	ABSENCE	ABSENCE	< 1
BRGY. MALUSAK							
05/19/2021 13:32	S21-3779	Santa Rosa City Hall	-	0.23	ABSENCE	ABSENCE	30
BRGY. SINALHAN							
05/19/2021 13:49	S21-3777	Block 8 Lot 16, Bayshore III	-	0.16	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. TAGAPO							
05/18/2021 12:37	S21-3756	#60 31 JP Rizal Boulevard	-	1.04	ABSENCE	ABSENCE	< 1
05/18/2021 13:16	S21-3758	Block 1 Lot 18, Fairfield of Margana Subdivision	-	1.10	ABSENCE	ABSENCE	< 1
05/18/2021 12:51	S21-3766	Water Pump, Rosewood Homes I	-	1.37	ABSENCE	ABSENCE	< 1
05/18/2021 12:58	S21-3767	Block 3 Lot 31, Rosewood Homes I	-	1.21	ABSENCE	ABSENCE	< 1
05/18/2021 13:29	S21-3768	Block 2 Lot 8, Rosewood Homes II	-	1.32	ABSENCE	ABSENCE	< 1
05/18/2021 12:00	S21-3757	Eye wash, Buena Rosa 1 Subdivision	-	0.15	ABSENCE	ABSENCE	< 1
05/18/2021 12:23	S21-3759	Block 1 Lot 64, Buena Rosa 10 Subdivision	-	0.11	ABSENCE	ABSENCE	< 1
05/18/2021 14:49	S21-3760	Cistern Tank, SM Santa Rosa	-	0.26	ABSENCE	ABSENCE	< 1
05/18/2021 14:56	S21-3761	Admin Pantry, SM Santa Rosa	-	0.21	ABSENCE	ABSENCE	< 1
05/19/2021 14:21	S21-3788	Cistern Tank, Robinson's Mall	-	0.12	ABSENCE	ABSENCE	< 1
05/18/2021 14:18	S21-3763	Ilonggo, Robinson's Mall	-	< 0.02	ABSENCE	ABSENCE	< 1
05/06/2021 14:29	S21-3377	Water Pump, Metrogate Heritage Subd.	7.60 / 27.0	0.40	ABSENCE	ABSENCE	< 1
05/06/2021 15:00	S21-3378	Clubhouse, Metrogate Heritage Subd.	7.45 / 26.1	0.36	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC – Heterotrophic Plate Count; CFU – Colony Forming Units; MDL – Method Detection Limit; LOQ – Limit of Quantification; NA – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: A – Electrometric; B – Colorimetric; C – Enzyme Substrate; D – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:


ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis