

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE I (CHO-1)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 22

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 04/01/2020-04/23/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C) MDL: NA LOQ: NA	RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	COLIFORM ^C		HPC ^D (CFU/mL)
		TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)				
BRGY. BIÑAN							
04/01/2020 14:11	S20-2006	Laguna Wellfield 1	7.52 / 28.6	0.69	ABSENCE	ABSENCE	1
BRGY. CAINGIN							
04/17/2020 12:38	S20-2532	Water Pump, Block 57, Phase 1, Southville	7.78 / 31.6	0.66	ABSENCE	ABSENCE	61
04/17/2020 13:16	S20-2533	Block 25 Lot 7, Phase 3, Southville	7.93 / 32.4	0.68	ABSENCE	ABSENCE	150
04/17/2020 12:44	S20-2534	Block 46 Lot 2, Phase 2, Southville	7.69 / 32.4	0.58	ABSENCE	ABSENCE	14
04/17/2020 12:50	S20-2536	Water Pump, Phase 8 & 9, Southville	8.11 / 30.9	1.40	ABSENCE	ABSENCE	68
04/17/2020 12:57	S20-2537	Block 9 Lot 32, Phase 8 & 9, Southville	7.94 / 31.2	1.28	ABSENCE	ABSENCE	380
04/17/2020 13:28	S20-2535	Water Pump, Phase 5, Southville	7.79 / 31.2	0.04	ABSENCE	ABSENCE	11
BRGY. KANLURAN							
04/17/2020 11:43	S20-2529	Gate Entrance, Alfonso Homes I	7.70 / 30.5	0.64	ABSENCE	ABSENCE	300
BRGY. MALUSAK							
04/17/2020 11:28	S20-2528	Santa Rosa City Hall	7.85 / 34.2	0.27	ABSENCE	ABSENCE	19
BRGY. MARKET AREA							
04/17/2020 11:02	S20-2526	Source, Market Area	6.97 / 30.7	0.23	ABSENCE	ABSENCE	24
BRGY. SINALHAN							
04/17/2020 10:49	S20-2525	Block 8 Lot 16, Bayshore III	6.78 / 31.8	0.26	ABSENCE	ABSENCE	-
04/17/2020 10:30	S20-2524	Amoranto Compound, Phase 2, Sinalhan	6.84 / 30.4	0.29	ABSENCE	ABSENCE	-
BRGY. TAGAPO							
04/23/2020 11:45	S20-2647	#60 31 JP Rizal Boulevard	7.14 / 29.7	0.72	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20						
04/23/2020 11:59	S20-2654	Block 1 Lot 18, Fairfield of Margana Subdivision	7.21 / 30.3	0.40	ABSENCE	ABSENCE	11
04/23/2020 12:11	S20-2655	Water Pump, Rosewood Homes I	7.15 / 29.6	0.42	ABSENCE	ABSENCE	9
04/23/2020 12:18	S20-2656	Block 3 Lot 31, Rosewood Homes I	7.22 / 30.2	0.38	ABSENCE	ABSENCE	16
04/23/2020 12:33	S20-2657	Block 4 Lot 1, Rosewood Homes II	7.18 / 29.4	0.35	ABSENCE	ABSENCE	5
04/23/2020 11:16	S20-2648	Clubhouse, Buena Rosa 1 Subdivision	7.16 / 30.1	0.47	ABSENCE	ABSENCE	< 1
04/23/2020 11:32	S20-2649	Block 1 Lot 64, Buena Rosa 10 Subdivision	7.19 / 29.6	0.42	ABSENCE	ABSENCE	< 1
04/23/2020 14:22	S20-2650	Cistern Tank, SM Sta. Rosa	7.22 / 29.7	0.32	ABSENCE	ABSENCE	< 1
04/23/2020 14:38	S20-2651	Admin Pantry, SM Sta. Rosa	7.18 / 30.7	0.25	ABSENCE	ABSENCE	< 1
04/23/2020 13:56	S20-2652	Cistern Tank, Robinson's Mall	7.22 / 29.6	0.15	ABSENCE	ABSENCE	< 1
04/23/2020 14:07	S20-2653	Shawarma, Robinson's Mall	7.28 / 30.1	0.10	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s): (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE II (CHO-2)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 47

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 04/01/2020-04/23/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. BIÑAN							
04/01/2020 14:11	S20-2006	Laguna Wellfield 1	7.52 / 28.6	0.69	ABSENCE	ABSENCE	1
BRGY. BALIBAGO							
04/23/2020 10:50	S20-2646	#1354 Facundo Compound	7.14 / 29.7	0.72	ABSENCE	ABSENCE	< 1
04/02/2020 11:20	S20-2031	5555 Water Pump Elevated, South Hampton	7.34 / 30.8	0.09	ABSENCE	ABSENCE	360
04/02/2020 11:32	S20-2032	Clubhouse, South Hampton	7.30 / 30.3	0.06	ABSENCE	ABSENCE	480
04/16/2020 14:10	S20-2518	Block 5 Lot 19, JB Village, Sta. Rosa Tagaytay Road	7.86 / 23.2	0.51	ABSENCE	ABSENCE	-
BRGY. DILA							
04/16/2020 13:18	S20-2509	Water Pump, Phase 3E, Mabuhay Homes 2000	7.45 / 32.8	0.18	ABSENCE	ABSENCE	< 1
04/16/2020 13:30	S20-2510	Block 2 Lot 10, Mabuhay Homes 2000	7.65 / 31.0	0.22	ABSENCE	ABSENCE	< 1
04/16/2020 13:44	S20-2511	Water Pump, Block 12, Phase 2E, Mabuhay Homes 2000	7.89 / 29.7	0.32	ABSENCE	ABSENCE	2
04/16/2020 15:53	S20-2512	Block 34 Lot 9, Phase 2E, Mabuhay Homes 2000	7.91 / 34.1	0.12	ABSENCE	ABSENCE	-
BRGY. DITA							
04/16/2020 12:43	S20-2513	Block 24 Lot 2, New Santa Rosa Homes	8.12 / 32.0	0.39	ABSENCE	ABSENCE	-
04/16/2020 12:51	S20-2514	Block 19 Lot 11, New Santa Rosa Homes	8.16 / 30.8	0.29	ABSENCE	ABSENCE	-
04/02/2020 11:44	S20-2033	Water Pump, Block 4 Lot 32, San Lorenzo Royale	7.27 / 20.4	0.34	ABSENCE	ABSENCE	< 1
04/02/2020 11:57	S20-2034	Block 11 Lot 52, San Lorenzo Royale	7.25 / 30.6	0.30	ABSENCE	ABSENCE	< 1
04/16/2020 12:04	S20-2515	Water Tank, SolCar Ville Subdivision	7.52 / 29.9	0.43	ABSENCE	ABSENCE	-
04/16/2020 12:24	S20-2516	Block 3 Lot 7, SolCar Ville Subdivision	7.90 / 30.4	0.42	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s) (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
04/02/2020 11:51	S20-2043	Block 29 Lot 16, Alabaster St., Villa Esmeralda	7.98 / 30.1	0.44	ABSENCE	ABSENCE	< 1
04/16/2020 13:04	S20-2522	#1780 National Road	7.94 / 29.2	0.54	ABSENCE	ABSENCE	-
04/16/2020 11:42	S20-2521	R & B Ice Plant, Inc.	7.88 / 32.0	0.74	ABSENCE	ABSENCE	-
BRGY. DON JOSE							
04/16/2020 12:09	S20-2474	Science High School, Phase 1, Laguna Bel-Air	7.16 / 29.8	0.38	ABSENCE	ABSENCE	1
04/16/2020 13:45	S20-2476	Church, Block 108, Phase 5, Laguna Bel-Air	7.27 / 29.5	0.29	ABSENCE	ABSENCE	< 1
04/16/2020 12:14	S20-2475	Block 34 Lot 59 Laguna Bel-Air I	7.22 / 29.6	0.47	ABSENCE	ABSENCE	< 1
04/16/2020 12:07	S20-2480	Block 47 Lot 12 Laguna Bel-Air IV	7.16 / 29.6	0.30	ABSENCE	ABSENCE	< 1
04/16/2020 10:41	S20-2468	8001, Pump 1, Acacia St., Santa Rosa Village I	7.19 / 29.7	0.33	ABSENCE	ABSENCE	36
04/16/2020 10:54	S20-2469	Clubhouse, Phase 4B, Santa Rosa Village I	7.16 / 30.1	0.30	ABSENCE	ABSENCE	23
04/16/2020 10:25	S20-2470	Clubhouse, Santa Rosa Village II	7.14 / 29.8	0.38	ABSENCE	ABSENCE	< 1
04/16/2020 11:13	S20-2471	Pump 9 & 10, Santa Rosa Estates I	7.18 / 28.9	0.27	ABSENCE	ABSENCE	18
04/16/2020 11:27	S20-2472	Clubhouse, Santa Rosa Estates I	7.21 / 29.3	0.38	ABSENCE	ABSENCE	1
04/16/2020 13:15	S20-2481	Drinking Fountain, Don Jose National High School	7.13 / 28.7	0.42	ABSENCE	ABSENCE	< 1
BRGY. MACABLING							
04/23/2020 13:17	S20-2658	Water Pump, Buena Rosa 9 Subdivision	7.14 / 29.7	0.55	ABSENCE	ABSENCE	2
04/23/2020 13:10	S20-2659	Block 4 Lot 26, Phase 1, Buena Rosa 9 Subdivision	7.23 / 30.6	0.42	ABSENCE	ABSENCE	5
04/23/2020 13:17	S20-2660	Water Pump, Corinthian Subdivision	7.25 / 29.7	0.16	ABSENCE	ABSENCE	< 1
04/23/2020 13:35	S20-2661	Block 11 Lot 19, Corinthian Subdivision	7.18 / 29.5	0.12	ABSENCE	ABSENCE	12
04/16/2020 11:09	S20-2519	Water Pump, Metrogate	6.98 / 29.6	0.57	ABSENCE	ABSENCE	-
04/16/2020 11:18	S20-2520	Gate Entrance, Metrogate	7.55 / 31.5	0.63	ABSENCE	ABSENCE	-
BRGY. MALITLIT							
04/16/2020 11:49	S20-2517	Clubhouse, Casan Residencia Subdivision	7.52 / 31.7	0.29	ABSENCE	ABSENCE	-
04/02/2020 12:04	S20-2035	Block 3 Lot 1, Phase 1A Annex, San Lorenzo Subd.	7.21 / 30.5	0.47	ABSENCE	ABSENCE	< 1
04/02/2020 12:11	S20-2036	Block 5 Lot 25, Phase 1A Annex, San Lorenzo Subd.	7.25 / 30.5	0.4	ABSENCE	ABSENCE	< 1
04/02/2020 12:19	S20-2039	Water Pump, Main Road, Phase 2, Terra Fortuna	7.23 / 29.5	0.15	ABSENCE	ABSENCE	< 1
04/02/2020 12:29	S20-2040	Block 11 Lot 16, Terra Fortuna	7.21 / 20.1	0.10	ABSENCE	ABSENCE	< 1
04/02/2020 12:50	S20-2037	9999 W, Villa Las Casas	7.14 / 29.4	0.30	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
04/02/2020 13:08	S20-2038	Block 1 Lot 17, Villa Las Casas	MDL: NA LOQ: NA 7.15 / 29.4	MDL: 0.06 LOQ: 0.20 0.27	ABSENCE	ABSENCE	< 1
BRGY. POOC							
04/17/2020 12:11	S20-2530	Water Pump, Villa Mercedes	7.53 / 31.2	0.85	ABSENCE	ABSENCE	27
04/17/2020 12:18	S20-2531	Block 2 Lot 1, Villa Mercedes	7.70 / 31.3	0.84	ABSENCE	ABSENCE	100
BRGY. PULONG STA. CRUZ							
04/02/2020 13:16	S20-2041	Drinking Fountain 1, Pulong Sta. Cruz Elementary School	7.54 / 30.4	0.57	ABSENCE	ABSENCE	< 1
04/02/2020 13:20	S20-2042	Drinking Fountain 2, Pulong Sta. Cruz Elementary School	7.34 / 30.6	0.55	ABSENCE	ABSENCE	< 1
04/02/2020 10:45	S20-2030	Lagatao Residence, Buklod Diwa	7.28 / 30.7	0.65	ABSENCE	ABSENCE	< 1
BRGY. SANTO DOMINGO							
04/16/2020 11:43	S20-2473	Clubhouse Santa Rosa Estates II	7.18 / 29.8	0.35	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: **A** – Electrometric; **B** – Colorimetric ; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR CODE



REVIEWED BY:


JETHRO D. ESCOBIN
Microbiology Unit Manager

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060958)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis