

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE I (CHO-1)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 24

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 02/24/2020-02/29/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. CAINGIN							
02/24/2020 10:47	S20-1133	Water Pump, Block 57, Phase 1, Southville	7.28 / 26.9	0.50	ABSENCE	ABSENCE	5
02/24/2020 10:59	S20-1134	Block 25 Lot 7, Phase 3, Southville	7.13 / 26.5	0.36	ABSENCE	ABSENCE	< 1
02/24/2020 11:20	S20-1138	Water Pump, Phase 9, Southville	7.15 / 26.5	0.25	ABSENCE	ABSENCE	< 1
02/24/2020 11:30	S20-1139	Santos Residence, Phase 9, Southville	7.13 / 26.4	0.21	ABSENCE	ABSENCE	< 1
BRGY. KANLURAN							
02/24/2020 12:05	S20-1128	#621 Rizal Boulevard	7.12 / 24.4	0.14	ABSENCE	ABSENCE	< 1
BRGY. LABAS							
02/24/2020 11:48	S20-1130	Block 18 Lot 2, Alfonso Homes I	7.24 / 27.8	0.25	ABSENCE	ABSENCE	16
BRGY. MALUSAK							
02/24/2020 12:21	S20-1135	Drinking Fountain 1, Central 1 Elementary School	7.12 / 26.4	0.34	ABSENCE	ABSENCE	< 1
02/24/2020 12:14	S20-1129	Drinking Fountain, Santa Rosa City Hall	7.05 / 27.6	0.25	ABSENCE	ABSENCE	< 1
BRGY. MARKET AREA							
02/24/2020 12:50	S20-1127	Source, Market Area	7.24 / 27.7	0.25	ABSENCE	ABSENCE	5
BRGY. SINALHAN							
02/24/2020 13:42	S20-1126	Block 8 Lot 16, Bayshore III	7.04 / 27.8	0.19	ABSENCE	ABSENCE	6
02/24/2020 14:00	S20-1124	4026, Sinalhan Road, Purok 2	7.34 / 27.0	0.27	ABSENCE	ABSENCE	1
02/24/2020 13:16	S20-1125	Amoranto Compound, Phase 2, Sinalhan	7.05 / 25.3	0.21	ABSENCE	ABSENCE	1
BRGY. TAGAPO							
02/27/2020 11:07	S20-1280	Water Pump, Fairfield of Margana Subdivision	7.44 / 29.6	0.06	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR STAMP

ANALYZED BY:

CERTIFIED CORRECT BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C) MDL: NA LOQ: NA	RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
02/27/2020 11:01	S20-1281	Block 2 Lot 21, Fairfield of Margana Subdivision	7.52 / 29.8	0.02	ABSENCE	ABSENCE	-
02/27/2020 10:38	S20-1282	Water Pump, Rosewood Homes I	7.66 / 29.9	1.19	ABSENCE	ABSENCE	-
02/27/2020 10:43	S20-1283	Block 3 Lot 31, Rosewood Homes I	7.66 / 29.5	1.07	ABSENCE	ABSENCE	-
02/27/2020 10:21	S20-1284	Block 2 Lot 8, Rosewood Homes II	7.54 / 29.6	0.86	ABSENCE	ABSENCE	-
02/27/2020 14:42	S20-1272	#60 31 JP Rizal Boulevard	7.46 / 29.4	0.89	ABSENCE	ABSENCE	-
02/27/2020 14:30	S20-1274	Water Pump, Buena Rosa 10 Subdivision	7.50 / 31.1	0.93	ABSENCE	ABSENCE	-
02/27/2020 14:20	S20-1275	Block 1 Lot 64, Buena Rosa 10 Subdivision	7.54 / 30.0	1.02	ABSENCE	ABSENCE	-
02/27/2020 15:39	S20-1276	Cistern Tank, SM Sta. Rosa	7.79 / 29.5	0.74	ABSENCE	ABSENCE	-
02/27/2020 15:47	S20-1277	Admin Pantry, SM Sta. Rosa	7.70 / 29.3	0.78	ABSENCE	ABSENCE	-
02/27/2020 15:07	S20-1278	Cistern Tank, Robinson's Mall	7.82 / 28.7	0.37	ABSENCE	ABSENCE	-
02/27/2020 15:17	S20-1279	Sizzler's, Robinson's Mall	7.81 / 25.7	0.25	ABSENCE	ABSENCE	-

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR STAMP

ANALYZED BY:

CERTIFIED CORRECT BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE II (CHO-2)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 51

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 02/12/2020-02/28/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. BALIBAGO							
02/27/2020 13:54	S20-1271	#1354 Facundo Compound	7.32 / 29.6	0.92	ABSENCE	ABSENCE	-
02/12/2020 10:51	S20-1051	Clubhouse, South Hampton	7.10 / 28.9	0.77	ABSENCE	ABSENCE	2
02/27/2020 17:20	S20-1302	Block 5 Lot 19, JB Village, Sta. Rosa Tagaytay Road	7.24 / 26.4	0.55	ABSENCE	ABSENCE	-
02/24/2020 11:23	S20-1154	Cistern Tank, Walter Mart	7.74 / 30.2	0.25	ABSENCE	ABSENCE	43
02/24/2020 11:16	S20-1155	2nd Floor Faucet, Walter Mart	7.40 / 29.3	0.53	ABSENCE	ABSENCE	< 1
BRGY. DILA							
02/27/2020 15:30	S20-1290	Water Pump, Phase 3E, Mabuhay Homes 2000	7.16 / 28.3	0.47	ABSENCE	ABSENCE	-
02/27/2020 15:40	S20-1291	Block 2 Lot 10, Mabuhay Homes 2000	7.40 / 27.6	0.36	ABSENCE	ABSENCE	-
02/27/2020 15:48	S20-1292	Water Pump, Block 12, Phase 2E, Mabuhay Homes 2000	7.15 / 27.5	0.50	ABSENCE	ABSENCE	-
02/27/2020 15:57	S20-1293	Block 13 Lot 5, Phase 2E, Mabuhay Homes 2000	7.14 / 27.5	0.48	ABSENCE	ABSENCE	-
02/27/2020 16:15	S20-1294	Drinking Fountain, Dila Elementary School	7.13 / 27.5	0.38	ABSENCE	ABSENCE	-
BRGY. DITA							
02/27/2020 15:12	S20-1295	Block 24 Lot 2, New Santa Rosa Homes	7.25 / 27.8	0.76	ABSENCE	ABSENCE	-
02/27/2020 12:15	S20-1296	Block 19 Lot 11, New Santa Rosa Homes	7.13 / 28.5	0.68	ABSENCE	ABSENCE	-
02/12/2020 12:21	S20-1028	Clubhouse, San Lorenzo Royale	7.21 / 29.3	0.72	ABSENCE	ABSENCE	45
02/27/2020 14:50	S20-1297	Water Tank, SolCar Ville Subdivision	7.36 / 27.3	0.86	ABSENCE	ABSENCE	-
02/27/2020 14:57	S20-1298	Block 3 Lot 7, SolCar Ville Subdivision	7.25 / 27.0	0.76	ABSENCE	ABSENCE	-
02/12/2020 12:10	S20-1037	Clubhouse, Villa Esmeralda	7.23 / 29.3	0.80	ABSENCE	ABSENCE	< 1
02/27/2020 15:34	S20-1306	#1780 National Road	7.25 / 28.0	0.68	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR STAMP

ANALYZED BY:

CERTIFIED CORRECT BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
02/27/2020 14:15	S20-1305	R & B Ice Plant, Inc.	7.29 / 27.9	0.88	ABSENCE	ABSENCE	-
BRGY. DON JOSE							
02/26/2020 13:28	S20-1219	Science High School, Phase 1, Laguna Bel-Air	7.15 / 26.5	0.36	ABSENCE	ABSENCE	-
02/26/2020 13:40	S20-1220	Block 34 Lot 59, Laguna Bel-Air	7.17 / 27.0	0.90	ABSENCE	ABSENCE	-
02/26/2020 12:59	S20-1221	Church, Block 108, Phase 5, Laguna Bel-Air	7.18 / 32.0	0.70	ABSENCE	ABSENCE	-
02/26/2020 14:30	S20-1225	Block 47 Lot 12 Laguna Bel-Air IV	7.40 / 27.5	0.36	ABSENCE	ABSENCE	-
02/26/2020 11:45	S20-1213	8001, Pump 1, Acacia St., Santa Rosa Village I	7.28 / 24.8	0.61	ABSENCE	ABSENCE	-
02/26/2020 11:29	S20-1214	Clubhouse, Phase 4B, Santa Rosa Village I	7.30 / 27.6	0.49	ABSENCE	ABSENCE	-
02/26/2020 11:25	S20-1215	Clubhouse, Santa Rosa Village II	7.34 / 26.4	0.80	ABSENCE	ABSENCE	-
02/26/2020 11:50	S20-1216	Pump 9 & 10, Santa Rosa Estates I	7.32 / 27.9	0.68	ABSENCE	ABSENCE	-
02/26/2020 12:11	S20-1217	Clubhouse, Santa Rosa Estates I	7.25 / 27.9	0.45	ABSENCE	ABSENCE	-
02/26/2020 14:40	S20-1226	Drinking Fountain, Don Jose National High School	7.48 / 27.0	1.31	ABSENCE	ABSENCE	-
BRGY. MACABLING							
02/27/2020 09:31	S20-1285	Water Pump, Buena Rosa 9 Subdivision	7.60 / 29.1	0.01	ABSENCE	ABSENCE	-
02/27/2020 09:37	S20-1286	Block 4 Lot 44, Phase 1, Buena Rosa 9 Subdivision	7.54 / 28.9	0.01	ABSENCE	ABSENCE	-
02/27/2020 09:16	S20-1287	Water Pump, Corinthian Subdivision	7.32 / 29.9	0.85	ABSENCE	ABSENCE	-
02/27/2020 09:16	S20-1288	Block 11 Lot 19, Corinthian Subdivision	7.15 / 29.0	0.63	ABSENCE	ABSENCE	-
02/27/2020 16:19	S20-1303	Water Pump, Metrogate	7.20 / 27.6	0.78	ABSENCE	ABSENCE	-
02/27/2020 16:30	S20-1304	Clubhouse, Metrogate	7.18 / 27.9	0.74	ABSENCE	ABSENCE	-
BRGY. MALITLIT							
02/27/2020 14:28	S20-1299	Water Pump, Casan Residencia Subdivision	7.21 / 27.9	0.70	ABSENCE	ABSENCE	-
02/27/2020 14:37	S20-1300	Clubhouse, Casan Residencia Subdivision	7.17 / 27.7	0.68	ABSENCE	ABSENCE	-
02/12/2020 11:30	S20-1029	Block 3 Lot 1, Phase 1A Annex, San Lorenzo Subd.	7.32 / 29.0	0.47	ABSENCE	ABSENCE	16
02/12/2020 13:36	S20-1030	Block 5 Lot 25, Phase 1A Annex, San Lorenzo Subd.	7.19 / 28.7	0.49	ABSENCE	ABSENCE	< 1
02/12/2020 11:54	S20-1033	Main Road, Phase 2, Terra Fortuna	7.11 / 28.6	1.08	ABSENCE	ABSENCE	28
02/12/2020 11:51	S20-1034	Block 11 Lot 16, Terra Fortuna	7.42 / 28.6	0.55	ABSENCE	ABSENCE	1
02/12/2020 11:18	S20-1031	9999 W, Villa Las Casas	7.28 / 28.8	1.11	ABSENCE	ABSENCE	14
02/12/2020 11:05	S20-1032	Block 1 Lot 17, Villa Las Casas	7.11 / 28.6	1.08	ABSENCE	ABSENCE	2
02/27/2020 17:55	S20-1301	Drinking Fountain, Malitlit Elementary School	7.18 / 26.7	0.63	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR STAMP

ANALYZED BY:

CERTIFIED CORRECT BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. POOC							
02/24/2020 09:50	S20-1136	Water Pump, Alinsod	7.18 / 27.8	0.34	ABSENCE	ABSENCE	1
02/24/2020 10:36	S20-1131	Water Pump, Villa Mercedes	7.15 / 27.6	0.10	ABSENCE	ABSENCE	16
02/24/2020 10:40	S20-1132	Block 2 Lot 1, Villa Mercedes	7.13 / 27.8	0.07	ABSENCE	ABSENCE	12
02/12/2020 10:31	S20-1035	Drinking Fountain 1, Pulong Sta.Cruz Elementary School	6.95 / 28.2	0.79	ABSENCE	ABSENCE	< 1
02/12/2020 10:24	S20-1036	Drinking Fountain 2, Pulong Sta.Cruz Elementary School	7.19 / 28.0	0.78	ABSENCE	ABSENCE	< 1
02/12/2020 10:02	S20-1026	Block 6 Lot 8, Buklod Diwa	7.26 / 27.6	0.82	ABSENCE	ABSENCE	3
02/24/2020 11:07	S20-1135	Block 46 Lot 2, Phase 2, Southville	7.12 / 26.4	0.34	ABSENCE	ABSENCE	< 1
BRGY. SANTO DOMINGO							
02/26/2020 13:20	S20-13:20	Clubhouse Santa Rosa Estates II	7.20 / 28.0	0.34	ABSENCE	ABSENCE	-

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric ; **C**- Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR STAMP

ANALYZED BY:

CERTIFIED CORRECT BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis