

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE I (CHO-1)

### SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 26

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 01/22/2020-01/29/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
<b>BRGY. CAINGIN</b>							
01/27/2020 11:00	S20-0526	Water Pump, Block 57, Phase 1, Southville	7.26 / 27.5	0.50	ABSENCE	ABSENCE	-
01/27/2020 11:15	S20-0527	Block 25 Lot 7, Phase 3, Southville	7.28 / 27.7	0.30	ABSENCE	ABSENCE	-
01/27/2020 12:00	S20-0531	Water Pump, Phase 9, Southville	7.28 / 27.6	0.45	ABSENCE	ABSENCE	-
01/27/2020 12:55	S20-0532	Santos Residence, Phase 9, Southville	7.20 / 27.5	0.39	ABSENCE	ABSENCE	-
<b>BRGY. KANLURAN</b>							
01/27/2020 13:30	S20-0521	#621 Rizal Boulevard	7.50 / 27.8	0.15	ABSENCE	ABSENCE	-
<b>BRGY. LABAS</b>							
01/27/2020 13:00	S20-0523	Block 18 Lot 2, Alfonso Homes I	7.30 / 28.6	0.10	ABSENCE	ABSENCE	-
<b>BRGY. MALUSAK</b>							
01/27/2020 10:40	S20-0530	Drinking Fountain 1, Central 1 Elementary School	7.30 / 25.6	0.35	ABSENCE	ABSENCE	-s
01/27/2020 13:20	S20-0522	Drinking Fountain, Santa Rosa City Hall	7.40 / 27.5	0.13	ABSENCE	ABSENCE	-
<b>BRGY. MARKET AREA</b>							
01/27/2020 12:39	S20-0520	Source, Market Area	7.62 / 27.6	0.12	ABSENCE	ABSENCE	-
<b>BRGY. SINALHAN</b>							
01/27/2020 14:30	S20-0519	Block 8 Lot 16, Bayshore III	7.40 / 27.6	0.90	ABSENCE	ABSENCE	-
01/27/2020 14:00	S20-0517	4026, Sinalhan Road, Purok 2	7.62 / 30.8	0.18	ABSENCE	ABSENCE	-
01/27/2020 14:20	S20-0518	Amoranto Compund, Phase 2, Sinalhan	7.25 / 28.5	0.10	ABSENCE	ABSENCE	-
<b>BRGY. TAGAPO</b>							
01/22/2020 13:25	S20-0458	Water Pump, Fairfield of Margana Subdivision	7.40 / 29.3	0.06	ABSENCE	ABSENCE	5

NOT VALID WITHOUT QR STAMP



ORIG



**TR20-0275**  
February 3, 2020 8:55 PM

ANALYZED BY:

JETHRO D. ESCOBIN  
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager, OIC  
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

**ADDRESS:** 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

**CONTACT NO.:** (049) 543-1916

**WEBSITE:** [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20						
01/22/2020 13:12	S20-0459	Block 2 Lot 21, Fairfield of Margana Subdivision	7.43 / 29.3	0.04	ABSENCE	ABSENCE	25
01/22/2020 12:48	S20-0460	Water Pump, Rosewood Homes I	7.60 / 28.9	0.46	ABSENCE	ABSENCE	< 1
01/22/2020 12:54	S20-0461	Block 3 Lot 31, Rosewood Homes I	7.64 / 29.0	0.50	ABSENCE	ABSENCE	< 1
01/22/2020 13:36	S20-0462	Block 4 Lot 1, Rosewood Homes II	7.55 / 29.6	0.50	ABSENCE	ABSENCE	1
01/22/2020 14:16	S20-0450	#60 31 JP Rizal Boulevard	7.60 / 30.9	0.42	ABSENCE	ABSENCE	< 1
01/22/2020 10:52	S20-0467	Water Pump, Buena Rosa 1 Subdivision	7.62 / 28.9	0.41	ABSENCE	ABSENCE	< 1
01/22/2020 10:53	S20-0451	Block 2 Lot 50, Buena Rosa 1 Subdivision	7.61 / 29.3	0.25	ABSENCE	ABSENCE	2
01/22/2020 13:57	S20-0452	Water Pump, Buena Rosa 10 Subdivision	7.72 / 30.1	0.03	ABSENCE	ABSENCE	34
01/22/2020 14:04	S20-0453	Block 1 Lot 64, Buena Rosa 10 Subdivision	7.73 / 30.0	0.02	ABSENCE	ABSENCE	< 1
01/22/2020 11:13	S20-0454	Cistern Tank, SM Sta. Rosa	7.55 / 28.4	0.75	ABSENCE	ABSENCE	< 1
01/22/2020 11:21	S20-0455	Admin Pantry, SM Sta. Rosa	7.57 / 27.1	0.85	ABSENCE	ABSENCE	< 1
01/22/2020 11:51	S20-0456	Cistern Tank, Robinson's Mall	7.87 / 29.3	0.16	ABSENCE	ABSENCE	< 1
01/22/2020 12:00	S20-0467	Hog Me, Robinson's Mall	7.81 / 27.4	0.12	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23<sup>rd</sup> Edition

NOT VALID WITHOUT QR STAMP



O  
R  
I  
G



TR20-0275

February 3, 2020 8:55 PM

ANALYZED BY:

JETHRO D. ESCOBIN  
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager, OIC  
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna  
CONTACT NO.: (049) 543-1916  
WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

**CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)**

**ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna**

**ATTENTION : SANTA ROSA CITY HEALTH OFFICE II (CHO-2)**

### SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 51

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 01/21/2020-01/30/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
<b>BRGY. BALIBAGO</b>							
01/22/2020 15:12	S20-0449	#1354 Facundo Compound	7.28 / 27.3	1.24	ABSENCE	ABSENCE	< 1
01/28/2020 10:22	S20-0536	5555 Water Pump Elevated, South Hampton	7.91 / 29.5	0.43	ABSENCE	ABSENCE	< 1
01/28/2020 10:29	S20-0537	Clubhouse, South Hampton	7.91 / 29.5	0.08	ABSENCE	ABSENCE	25
01/22/2020 11:00	S20-0504	Block 5 Lot 19, JB Village, Sta. Rosa Tagaytay Road	7.26 / 26.6	0.50	ABSENCE	ABSENCE	-
01/28/2020 12:51	S20-0533	Cistern Tank, Walter Mart	7.58 / 30.8	0.21	ABSENCE	ABSENCE	< 1
01/28/2020 12:38	S20-0534	2nd Floor Faucet, Walter Mart	7.52 / 30.4	0.17	ABSENCE	ABSENCE	5
<b>BRGY. DILA</b>							
01/22/2020 13:30	S20-0493	Water Pump, Phase 3E, Mabuhay Homes 2000	7.72 / 28.3	0.26	ABSENCE	ABSENCE	-
01/22/2020 13:25	S20-0494	Block 2 Lot 10, Mabuhay Homes 2000	7.23 / 28.4	0.05	ABSENCE	ABSENCE	-
01/22/2020 13:00	S20-0495	Water Pump, Block 12, Phase 2E, Mabuhay Homes 2000	7.16 / 28.5	0.21	ABSENCE	ABSENCE	-
01/22/2020 13:30	S20-0496	Block 13 Lot 5, Phase 2E, Mabuhay Homes 2000	7.27 / 27.3	0.27	ABSENCE	ABSENCE	-
01/22/2020 12:40	S20-0497	Drinking Fountain, Dila Elementary School	6.87 / 29.7	1.55	ABSENCE	ABSENCE	-
<b>BRGY. DITA</b>							
01/22/2020 12:05	S20-0498	Block 24 Lot 2, New Santa Rosa Homes	7.62 / 29.3	0.35	ABSENCE	ABSENCE	-
01/22/2020 12:15	S20-0499	Block 24 Lot 5, New Santa Rosa Homes	7.67 / 27.6	0.42	ABSENCE	ABSENCE	-
01/28/2020 12:04	S20-0538	Clubhouse, San Lorenzo Royale	7.49 / 30.5	0.45	ABSENCE	ABSENCE	4
01/22/2020 12:05	S20-0500	Water Tank, SolCar Ville Subdivision	7.32 / 28.3	0.66	ABSENCE	ABSENCE	-
01/22/2020 10:30	S20-0501	Block 3 Lot 7, SolCar Ville Subdivision	7.37 / 27.2	0.33	ABSENCE	ABSENCE	-
01/28/2020 12:15	S20-0547	Clubhouse, Villa Esmeralda	7.26 / 29.9	0.48	ABSENCE	ABSENCE	< 1
01/22/2020 11:20	S20-0508	#1780 National Road	6.35 / 29.5	1.37	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR STAMP



QR  
I  
G



**TR20-0276**  
February 3, 2020 8:59 PM

ANALYZED BY:

JETHRO D. ESCOBIN  
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

ANNA KARIA GUTERREZ, RMT  
Laboratory Services Manager, OIC  
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis



ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
01/22/2020 14:30	S20-0507	R & B Ice Plant, Inc.	7.29 / 27.8	1.54	ABSENCE	ABSENCE	-
<b>BRGY. DON JOSE</b>							
01/21/2020 14:35	S20-0414	Science High School, Phase 1, Laguna Bel-Air	7.09 / 26.5	1.10	ABSENCE	ABSENCE	-
01/21/2020 14:25	S20-0415	Block 34 Lot 59, Laguna Bel-Air	7.08 / 28.8	0.90	ABSENCE	ABSENCE	-
01/21/2020 14:25	S20-0416	Church, Block 108, Phase 5, Laguna Bel-Air	7.00 / 28.8	1.01	ABSENCE	ABSENCE	-
01/21/2020 14:59	S20-0420	Block 47 Lot 12 Laguna Bel-Air IV	7.08 / 28.8	1.05	ABSENCE	ABSENCE	-
01/21/2020 16:20	S20-0408	8001, Pump 1, Acacia St., Santa Rosa Village I	7.14 / 26.6	0.60	ABSENCE	ABSENCE	-
01/21/2020 16:50	S20-0409	Clubhouse, Phase 4B, Santa Rosa Village I	7.50 / 27.5	0.60	ABSENCE	ABSENCE	-
01/21/2020 16:58	S20-0410	Clubhouse, Santa Rosa Village II	7.08 / 27.1	0.44	ABSENCE	ABSENCE	-
01/21/2020 15:38	S20-0411	Pump 9 & 10, Santa Rosa Estates I	7.12 / 26.9	0.40	ABSENCE	ABSENCE	-
01/21/2020 15:50	S20-0412	Clubhouse, Santa Rosa Estates I	7.09 / 27.4	0.38	ABSENCE	ABSENCE	-
01/21/2020 15:00	S20-0421	Drinking Fountain, Don Jose National High School	7.61 / 27.5	0.02	ABSENCE	ABSENCE	-
<b>BRGY. MACABLING</b>							
01/22/2020 10:17	S20-0463	Water Pump, Buena Rosa 9 Subdivision	7.54 / 28.8	1.05	ABSENCE	ABSENCE	15
01/22/2020 10:24	S20-0464	Block 4 Lot 26, Phase 1, Buena Rosa 9 Subdivision	7.48 / 29.2	1.08	ABSENCE	ABSENCE	< 1
01/22/2020 09:54	S20-0465	Water Pump, Corinthian Subdivision	7.35 / 29.0	0.19	ABSENCE	ABSENCE	< 1
01/22/2020 10:03	S20-0466	Block 11 Lot 19, Corinthian Subdivision	7.43 / 29.1	0.28	ABSENCE	ABSENCE	< 1
01/22/2020 14:46	S20-0505	Water Pump, Metrogate	7.25 / 27.5	0.90	ABSENCE	ABSENCE	-
01/22/2020 14:59	S20-0506	Clubhouse, Metrogate	7.24 / 26.6	0.60	ABSENCE	ABSENCE	-
<b>BRGY. MALITLIT</b>							
01/22/2020 15:30	S20-0502	Water Pump, Casan Residencia Subdivision	7.51 / 27.9	0.40	ABSENCE	ABSENCE	-
01/22/2020 15:40	S20-0503	Clubhouse, Casan Residencia Subdivision	7.50 / 24.8	0.35	ABSENCE	ABSENCE	-
01/28/2020 11:16	S20-0539	Block 3 Lot 1, Phase 1A Annex, San Lorenzo Subd.	7.12 / 30.0	0.57	ABSENCE	ABSENCE	< 1
01/28/2020 12:51	S20-0540	Block 5 Lot 25, Phase 1A Annex, San Lorenzo Subd.	7.02 / 29.1	0.45	ABSENCE	ABSENCE	< 1
01/28/2020 11:43	S20-0543	Main Road, Phase 2, Terra Fortuna	7.33 / 29.3	0.89	ABSENCE	ABSENCE	9
01/28/2020 11:51	S20-0544	Block 11 Lot 16, Terra Fortuna	7.32 / 29.1	0.78	ABSENCE	ABSENCE	< 1
01/28/2020 11:02	S20-0541	9999 W, Villa Las Casas	7.11 / 29.2	0.82	ABSENCE	ABSENCE	< 1
01/28/2020 10:47	S20-0542	Block 1 Lot 17, Villa Las Casas	7.03 / 29.1	0.73	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR STAMP



O  
R  
I  
G



TR20-0276

February 3, 2020 8:59 PM

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ANALYZED BY:

*Jethro D. Escobin*  
JETHRO D. ESCOBIN  
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

*Anna Karla S. Gutierrez*  
ANNA KARIA S. GUTIERREZ, RMT  
Laboratory Services Manager, OIC  
PRC License No. 0060958

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: [www.lagunawater.com.ph](http://www.lagunawater.com.ph)

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature <sup>A</sup> (- / °C)	RESIDUAL CHLORINE <sup>B</sup> (mg/L)	COLIFORM <sup>C</sup>		HPC <sup>D</sup> (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
<b>BRGY. POOC</b>							
01/27/2020 11:28	S20-0529	Water Pump, Alinsod	7.29 / 28.7	0.40	ABSENCE	ABSENCE	-
01/27/2020 10:40	S20-0524	Water Pump, Villa Mercedes	7.50 / 29.8	0.10	ABSENCE	ABSENCE	-
01/27/2020 10:57	S20-0525	Block 2 Lot 1, Villa Mercedes	7.48 / 27.5	0.08	ABSENCE	ABSENCE	-
01/28/2020 10:09	S20-0545	Drinking Fountain 1, Pulong Sta. Cruz Elementary School	7.32 / 29.1	0.78	ABSENCE	ABSENCE	< 1
01/28/2020 10:03	S20-0546	Drinking Fountain 2, Pulong Sta. Cruz Elementary School	6.70 / 28.5	0.83	ABSENCE	ABSENCE	< 1
01/28/2020 13:16	S20-0535	Block 6 Lot 8, Buklod Diwa	7.03 / 30.8	0.95	ABSENCE	ABSENCE	< 1
01/27/2020 11:28	S20-0529	Block 46 Lot 2, Phase 2, Southville	7.26 / 28.5	0.25	ABSENCE	ABSENCE	-
<b>BRGY. SANTO DOMINGO</b>							
01/21/2020 14:23	S20-0413	Clubhouse Santa Rosa Estates II	7.04 / 27.4	0.34	ABSENCE	ABSENCE	-

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23<sup>rd</sup> Edition

NOT VALID WITHOUT QR STAMP



O  
R  
I  
G




TR20-0276


February 3, 2020 8:59 PM

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ANALYZED BY:

  
JETHRO D. ESCOBIN  
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

  
ANNA KARLA S. GUTIERREZ, RMT  
Laboratory Services Manager, OIC  
PRC License No. 0060968