

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE I (CHO-1)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 26

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 03/05/2020-03/13/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. CAINGIN							
03/05/2020 09:45	S20-1511	Water Pump, Block 57, Phase 1, Southville	7.58 / 31.6	0.82	ABSENCE	ABSENCE	-
03/05/2020 11:01	S20-1512	Block 25 Lot 7, Phase 3, Southville	7.61 / 31.8	0.94	ABSENCE	ABSENCE	-
03/05/2020 13:40	S20-1514	Water Pump, Phase 8 & 9, Southville	7.52 / 30.5	0.12	ABSENCE	ABSENCE	-
03/05/2020 10:18	S20-1516	Block 2 Lot 16, Phase 8 & 9, Southville	7.54 / 31.3	0.11	ABSENCE	ABSENCE	-
03/05/2020 11:12	S20-1517	Water Pump, Phase 5, Southville	7.68 / 31.0	0.13	ABSENCE	ABSENCE	-
BRGY. LABAS							
03/05/2020 11:33	S20-1508	Block 18 Lot 2, Alfonso Homes I	7.24 / 28.5	0.72	ABSENCE	ABSENCE	-
BRGY. MALUSAK							
03/05/2020 13:40	S20-1514	Drinking Fountain 1, Central 1 Elementary School	7.52 / 30.5	0.67	ABSENCE	ABSENCE	-
03/05/2020 12:07	S20-1507	City Health Office I	7.22 / 31.6	0.23	ABSENCE	ABSENCE	-
BRGY. MARKET AREA							
03/05/2020 13:13	S20-1505	Source, Market Area	7.80 / 31.2	0.40	ABSENCE	ABSENCE	-
BRGY. SINALHAN							
03/05/2020 13:21	S20-1504	Block 8 Lot 16, Bayshore III	7.56 / 30.4	0.40	ABSENCE	ABSENCE	-
03/05/2020 12:40	S20-1502	4026, Sinalhan Road, Purok 2	7.58 / 31.9	0.16	ABSENCE	ABSENCE	-
03/05/2020 12:45	S20-1503	Amoranto Compound, Phase 2, Sinalhan	7.88 / 30.0	0.11	ABSENCE	ABSENCE	-
BRGY. TAGAPO							
03/13/2020 14:29	S20-1825	#60 31 JP Rizal Boulevard	7.31 / 28.9	0.35	ABSENCE	ABSENCE	21
03/13/2020 14:08	S20-1834	Water Pump, Fairfield of Margana Subdivision	7.27 / 30.6	0.14	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR STAMP



ANALYZED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C) MDL: NA LOQ: NA	RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	COLIFORM ^C		HPC ^D (CFU/mL)
			TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)			
03/13/2020 14:17	S20-1835	Block 1 Lot 18, Fairfield of Margana Subdivision	7.28 / 30.4	0.10	ABSENCE	ABSENCE	< 1
03/13/2020 13:17	S20-1836	Water Pump, Rosewood Homes I	7.29 / 27.8	0.61	ABSENCE	ABSENCE	< 1
03/13/2020 13:26	S20-1837	Block 3 Lot 31, Rosewood Homes I	7.25 / 28.1	0.58	ABSENCE	ABSENCE	< 1
03/13/2020 13:48	S20-1838	Block 4 Lot 1, Rosewood Homes II	7.27 / 28.5	0.35	ABSENCE	ABSENCE	< 1
03/13/2020 15:51	S20-1826	Water Pump, Buena Rosa 1 Subdivision	7.29 / 29.1	0.25	ABSENCE	ABSENCE	8
03/13/2020 16:12	S20-1827	Clubhouse, Buena Rosa 1 Subdivision	7.30 / 29.1	0.18	ABSENCE	ABSENCE	11
03/13/2020 12:57	S20-1828	Water Pump, Buena Rosa 10 Subdivision	7.52 / 28.5	0.22	ABSENCE	ABSENCE	28
03/13/2020 13:05	S20-1829	Block 1 Lot 64, Buena Rosa 10 Subdivision	7.54 / 28.0	0.15	ABSENCE	ABSENCE	< 1
03/13/2020 13:30	S20-1830	Cistern Tank, SM Sta. Rosa	7.55 / 28.5	0.68	ABSENCE	ABSENCE	25
03/13/2020 13:36	S20-1831	Admin Pantry, SM Sta. Rosa	7.66 / 28.7	0.65	ABSENCE	ABSENCE	< 1
03/13/2020 14:36	S20-1832	Cistern Tank, Robinson's Mall	7.74 / 30.3	0.32	ABSENCE	ABSENCE	< 1
03/13/2020 14:52	S20-1833	Ricky Li, Robinson's Mall	7.72 / 29.8	0.35	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR STAMP



TR20-0822
March 24, 2020 3:03 PM

ANALYZED BY:

Jethro D. Escobin
JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

Anna Karla S. Gutierrez
ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE II (CHO-2)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 49

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 03/03/2020-03/18/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. BALIBAGO							
03/13/2020 11:10	S20-1843	#1354 Facundo Compound	7.35 / 29.1	0.50	ABSENCE	ABSENCE	< 1
03/03/2020 13:00	S20-1425	5555 Water Pump Elevated, South Hampton	7.50 / 30.0	0.05	ABSENCE	ABSENCE	-
03/03/2020 13:15	S20-1426	Clubhouse, South Hampton	7.37 / 27.5	0.03	ABSENCE	ABSENCE	-
03/11/2020 10:20	S20-1741	Block 5 Lot 19, JB Village, Sta. Rosa Tagaytay Road	7.69 / 29.1	0.76	ABSENCE	ABSENCE	-
BRGY. DILA							
03/11/2020 11:30	S20-1730	Water Pump, Phase 3E, Mabuhay Homes 2000	7.31 / 32.3	0.16	ABSENCE	ABSENCE	< 1
03/11/2020 11:40	S20-1731	Block 2 Lot 10, Mabuhay Homes 2000	7.52 / 32.4	0.05	ABSENCE	ABSENCE	19
03/11/2020 11:55	S20-1732	Water Pump, Block 12, Phase 2E, Mabuhay Homes 2000	7.79 / 30.4	0.32	ABSENCE	ABSENCE	1
03/11/2020 12:05	S20-1733	Block 34 Lot 9, Phase 2E, Mabuhay Homes 2000	7.60 / 31.4	0.06	ABSENCE	ABSENCE	< 1
03/11/2020 10:41	S20-1734	Drinking Fountain, Dila Elementary School	7.48 / 30.3	0.72	ABSENCE	ABSENCE	< 1
BRGY. DITA							
03/11/2020 13:32	S20-1735	Block 24 Lot 2, New Santa Rosa Homes	7.95 / 31.2	0.61	ABSENCE	ABSENCE	< 1
03/11/2020 13:41	S20-1736	Block 19 Lot 11, New Santa Rosa Homes	7.92 / 31.0	0.60	ABSENCE	ABSENCE	< 1
03/03/2020 13:40	S20-1427	Water Pump, Block 4 Lot 32, San Lorenzo Royale	7.27 / 27.6	0.03	ABSENCE	ABSENCE	-
03/03/2020 13:59	S20-1428	Block 11 Lot 52, San Lorenzo Royale	7.27 / 27.8	0.57	ABSENCE	ABSENCE	-
03/11/2020 12:31	S20-1737	Water Tank, SolCar Ville Subdivision	7.77 / 30.2	0.75	ABSENCE	ABSENCE	< 1
03/13/2020 14:39	S20-1823	Block 3 Lot 7, SolCar Ville Subdivision	7.64 / 38.6	0.61	ABSENCE	ABSENCE	< 1
03/03/2020 13:38	S20-1437	Clubhouse, Villa Esmeralda	7.10 / 27.9	0.65	ABSENCE	ABSENCE	-
03/11/2020 13:55	S20-1745	#1780 National Road	7.63 / 29.1	0.79	ABSENCE	ABSENCE	220

NOT VALID WITHOUT QR STAMP



ANALYZED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
03/11/2020 14:05	S20-1744	R & B Ice Plant, Inc.	7.58 / 30.2	0.88	ABSENCE	ABSENCE	89
BRGY. DON JOSE							
03/16/2020 13:10	S20-1851	Science High School, Phase 1, Laguna Bel-Air	7.64 / 27.6	0.70	ABSENCE	ABSENCE	1
03/16/2020 13:18	S20-1852	Clubhouse, Laguna Bel-Air	7.59 / 29.3	0.71	ABSENCE	ABSENCE	< 1
03/16/2020 11:22	S20-1853	Church, Block 108, Phase 5, Laguna Bel-Air	7.50 / 30.3	0.58	ABSENCE	ABSENCE	< 1
03/16/2020 13:02	S20-1857	Block 47 Lot 12 Laguna Bel-Air IV	7.54 / 29.1	0.70	ABSENCE	ABSENCE	< 1
03/16/2020 10:01	S20-1845	8001, Pump 1, Acacia St., Santa Rosa Village I	7.38 / 27.1	0.37	ABSENCE	ABSENCE	< 1
03/16/2020 10:08	S20-1846	Clubhouse, Phase 4B, Santa Rosa Village I	7.56 / 29.0	0.62	ABSENCE	ABSENCE	< 1
03/16/2020 10:17	S20-1847	Clubhouse, Santa Rosa Village II	7.74 / 29.2	0.42	ABSENCE	ABSENCE	< 1
03/16/2020 10:29	S20-1848	Pump 9 & 10, Santa Rosa Estates I	7.62 / 28.1	0.41	ABSENCE	ABSENCE	4
03/16/2020 10:34	S20-1849	Clubhouse, Santa Rosa Estates I	7.59 / 29.0	0.40	ABSENCE	ABSENCE	< 1
03/16/2020 11:06	S20-1858	Drinking Fountain, Don Jose National High School	7.36 / 28.3	0.72	ABSENCE	ABSENCE	< 1
BRGY. MACABLING							
03/13/2020 12:06	S20-1839	Water Pump, Buena Rosa 9 Subdivision	7.47 / 28.5	0.69	ABSENCE	ABSENCE	< 1
03/13/2020 12:11	S20-1840	Block 4 Lot 26, Phase 1, Buena Rosa 9 Subdivision	7.47 / 29.3	0.60	ABSENCE	ABSENCE	< 1
03/13/2020 12:16	S20-1841	Water Pump, Corinthian Subdivision	7.32 / 29.0	0.35	ABSENCE	ABSENCE	< 1
03/13/2020 12:37	S20-1842	Block 11 Lot 19, Corinthian Subdivision	7.29 / 29.3	0.32	ABSENCE	ABSENCE	< 1
03/11/2020 09:46	S20-1742	Water Pump, Metrogate	7.67 / 30.1	0.84	ABSENCE	ABSENCE	210
03/13/2020 15:01	S20-1824	Gate Entrance, Metrogate	8.03 / 31.2	0.91	ABSENCE	ABSENCE	< 1
BRGY. MALITLIT							
03/11/2020 14:31	S20-1739	Water Pump, Casan Residencia Subdivision	7.70 / 29.6	0.61	ABSENCE	ABSENCE	< 1
03/11/2020 14:18	S20-1740	Clubhouse, Casan Residencia Subdivision	7.58 / 32.9	0.39	ABSENCE	ABSENCE	< 1
03/03/2020 13:50	S20-1429	Block 3 Lot 1, Phase 1A Annex, San Lorenzo Subd.	7.34 / 27.8	0.47	ABSENCE	ABSENCE	-
03/03/2020 14:50	S20-1450	Block 5 Lot 25, Phase 1A Annex, San Lorenzo Subd.	7.28 / 27.8	0.37	ABSENCE	ABSENCE	-
03/03/2020 14:15	S20-1433	Main Road, Phase 2, Terra Fortuna	7.44 / 28.1	0.18	ABSENCE	ABSENCE	-
03/03/2020 14:24	S20-1434	Block 11 Lot 16, Terra Fortuna	7.38 / 28.5	0.12	ABSENCE	ABSENCE	-
03/03/2020 15:10	S20-1431	9999 W, Villa Las Casas	7.38 / 27.6	0.35	ABSENCE	ABSENCE	-
03/03/2020 15:20	S20-1432	Block 1 Lot 17, Villa Las Casas	7.25 / 27.4	0.26	ABSENCE	ABSENCE	-

NOT VALID WITHOUT QR STAMP



TR20-0823

March 24, 2020 3:04 PM

O
R
I
G



ANALYZED BY:

JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060958

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20	TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. POOC							
03/05/2020 09:07	S20-1509	Water Pump, Villa Mercedes	6.88 / 29.7	0.98	ABSENCE	ABSENCE	-
03/05/2020 09:20	S20-1510	Block 2 Lot 1, Villa Mercedes	7.48 / 29.4	1.08	ABSENCE	ABSENCE	-
03/03/2020 12:23	S20-1435	Drinking Fountain 1, Pulong Sta. Cruz Elementary School	7.09 / 28.6	0.68	ABSENCE	ABSENCE	-
03/03/2020 12:10	S20-1436	Drinking Fountain 2, Pulong Sta. Cruz Elementary School	7.10 / 28.1	0.77	ABSENCE	ABSENCE	-
03/03/2020 11:50	S20-1424	Block 6 Lot 8, Buklod Diwa	7.05 / 27.8	0.83	ABSENCE	ABSENCE	-
03/05/2020 09:51	S20-1513	Southville National High School, Southville	7.82 / 31.2	1.01	ABSENCE	ABSENCE	-
BRGY. SANTO DOMINGO							
03/16/2020 10:49	S20-1850	Clubhouse Santa Rosa Estates II	7.73 / 28.9	0.40	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.

METHODS: **A** – Electrometric; **B** – Colorimetric ; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition

NOT VALID WITHOUT QR STAMP




O
R
I
G




TR20-0823

March 24, 2020 3:04 PM

ANALYZED BY:


JETHRO D. ESCOBIN
Microbiology Unit Manager, OIC

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager, OIC
PRC License No. 0060968

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis