

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE I (CHO-1)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 28

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 11/05/2020-11/27/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. BIÑAN							
11/04/2020 13:20	S20-7405	Laguna Wellfield 1	7.43 / 28.3	0.92	ABSENCE	ABSENCE	< 1
BRGY. CAINGIN							
11/10/2020 13:00	S20-7664	Water Pump, Block 57, Phase 1, Southville	7.48 / 27.8	0.24	ABSENCE	ABSENCE	2
11/10/2020 13:20	S20-7665	Block 25 Lot 7, Phase 3, Southville	7.56 / 27.7	0.19	ABSENCE	ABSENCE	3
11/10/2020 13:40	S20-7666	Block 46 Lot 2, Phase II, Southville	7.68 / 27.5	0.16	ABSENCE	ABSENCE	7
11/25/2020 14:32	S20-8089	Water Pump, Phase 8 & 9, Southville	-	0.46	ABSENCE	ABSENCE	< 1
11/25/2020 14:38	S20-8090	Block 16 Lot 2, Phase 9, Southville	-	0.45	ABSENCE	ABSENCE	< 1
11/25/2020 14:55	S20-8091	Water Pump, Phase 5, Southville	-	0.87	ABSENCE	ABSENCE	< 1
BRGY. KANLURAN							
11/10/2020 11:40	S20-7661	Block 18 Lot 2, Alfonso Homes I	7.45 / 27.4	0.34	ABSENCE	ABSENCE	< 1
11/10/2020 11:14	S20-7659	#621 Rizal Boulevard	7.51 / 27.8	0.16	ABSENCE	ABSENCE	< 1
BRGY. MALUSAK							
11/10/2020 11:25	S20-7669	Santa Rosa City Hall	7.68 / 27.5	0.38	ABSENCE	ABSENCE	< 1
11/10/2020 14:25	S20-7668	Drinking Fountain 1, Central Elementary School	7.77 / 27.5	0.36	ABSENCE	ABSENCE	< 1
BRGY. MARKET AREA							
11/10/2020 11:10	S20-7658	Water Pump	7.64 / 27.5	0.28	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060958)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER					
			pH/ Temperature ^A (- / °C) MDL: NA LOQ: NA	RESIDUAL CHLORINE ^B (mg/L) MDL: 0.06 LOQ: 0.20	COLIFORM ^C		HPC ^D (CFU/mL)	
			TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)				
BRGY. SINALHAN								
11/10/2020 10:41	S20-7656	Amoranto Compound, Purok II	7.56 / 27.0	0.29	ABSENCE	ABSENCE	< 1	
11/10/2020 10:59	S20-7657	Block 8 Lot 16, Bayshore III	7.68 / 26.7	0.31	ABSENCE	ABSENCE	1	
11/10/2020 10:30	S20-7655	Water Pump 4026, Sinalhan Road, Purok II	7.65 / 27.9	0.34	ABSENCE	ABSENCE	< 1	
BRGY. TAGAPO								
11/16/2020 11:41	S20-7780	#60 31 JP Rizal Boulevard	7.68 / 28.7	0.38	ABSENCE	ABSENCE	< 1	
11/16/2020 13:16	S20-7782	Block 1 Lot 18, Fairfield of Margana Subdivision	7.61 / 27.9	0.44	ABSENCE	ABSENCE	< 1	
11/16/2020 14:25	S20-7790	Water Pump, Rosewood Homes I	7.55 / 28.5	0.41	ABSENCE	ABSENCE	< 1	
11/16/2020 14:38	S20-7791	Block 3 Lot 31, Rosewood Homes I	7.60 / 29.9	0.38	ABSENCE	ABSENCE	< 1	
11/16/2020 14:45	S20-7792	Block 4 Lot 1, Rosewood Homes II	7.68 / 29.5	0.35	ABSENCE	ABSENCE	< 1	
11/16/2020 11:59	S20-7781	Clubhouse, Buena Rosa 1 Subdivision	7.58 / 27.8	0.30	ABSENCE	ABSENCE	< 1	
11/16/2020 12:28	S20-7783	Block 1 Lot 64, Buena Rosa 10 Subdivision	7.70 / 29.0	0.38	ABSENCE	ABSENCE	< 1	
11/16/2020 12:38	S20-7784	Cistern Tank, SM Sta. Rosa	7.40 / 28.0	0.10	ABSENCE	ABSENCE	< 1	
11/16/2020 12:49	S20-7785	Admin Pantry, SM Sta. Rosa	7.68 / 29.0	0.05	ABSENCE	ABSENCE	< 1	
11/16/2020 13:20	S20-7786	Cistern Tank, Robinson's Mall	7.55 / 28.8	0.06	ABSENCE	ABSENCE	< 1	
11/16/2020 13:33	S20-7787	Shawarma, Robinson's Mall	7.61 / 29.8	0.04	ABSENCE	ABSENCE	< 1	
11/05/2020 16:15	S20-7428	Water Pump, Metrogate Heritage Subd.	7.84 / 27.6	0.93	ABSENCE	ABSENCE	< 1	
11/05/2020 16:29	S20-7429	Guard house, Metrogate Heritage Subd.	7.90 / 29.0	0.74	ABSENCE	ABSENCE	< 1	

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: **HPC** – Heterotrophic Plate Count; **CFU** – Colony Forming Units; **MDL** – Method Detection Limit; **LOQ** – Limit of Quantification; **NA** – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: **A** – Electrometric; **B** – Colorimetric; **C** – Enzyme Substrate; **D** – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:


ALYSSA MARIE C. PINALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

CUSTOMER NAME : LAGUNA AAWATER CORPORATION (LAGUNA WATER)

ADDRESS : G/F One Evotech Building, Lakeside Evozone, Nuvali, Brgy. Santo Domingo, Santa Rosa City, Laguna

ATTENTION : SANTA ROSA CITY HEALTH OFFICE II (CHO-2)

SUMMARY OF LABORATORY ANALYSIS

NO. OF SAMPLES : 48

TOTAL PARAMETERS TESTED : 5

ANALYSIS DATE(S) : 11/05/2020-11/25/2020

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
			MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20			
BRGY. BIÑAN							
11/04/2020 13:20	S20-7405	Laguna Wellfield 1	7.43 / 28.3	0.92	ABSENCE	ABSENCE	< 1
BRGY. BALIBAGO							
11/16/2020 11:30	S20-7779	#1354 Facundo Compound	7.78 / 29.8	0.40	ABSENCE	ABSENCE	< 1
11/10/2020 11:16	S20-7594	Clubhouse, South Hampton	-	0.83	ABSENCE	ABSENCE	< 1
11/05/2020 13:55	S20-7427	Block 5 Lot 25, JB Village	7.80 / 27.5	0.26	ABSENCE	ABSENCE	< 1
11/23/2020 10:49	S20-8000	Cistern Tank, Waltermart Santa Rosa	-	0.39	ABSENCE	ABSENCE	< 1
11/23/2020 10:44	S20-8001	2 nd Floor, Waltermart, Santa Rosa	-	0.44	ABSENCE	ABSENCE	< 1
BRGY. DILA							
11/05/2020 15:20	S20-7415	Water Pump, Phase 3E, Mabuhay Homes 2000	7.68 / 27.8	0.35	ABSENCE	ABSENCE	< 1
11/05/2020 15:38	S20-7416	Block 2 Lot 10, Mabuhay Homes 2000	7.75 / 28.9	0.18	ABSENCE	ABSENCE	< 1
11/05/2020 15:10	S20-7417	Water Pump, Block 12, Phase 2E, Mabuhay Homes 2000	7.60 / 29.0	0.15	ABSENCE	ABSENCE	< 1
11/05/2020 14:56	S20-7418	Block 13 Lot 5, Phase 2E, Mabuhay Homes 2000	7.71 / 28.1	0.09	ABSENCE	ABSENCE	< 1
11/05/2020 14:30	S20-7419	Drinking Fountain, Dila Elementary School	7.80 / 29.8	0.06	ABSENCE	ABSENCE	< 1
11/10/2020 12:46	S20-7604	Block 29 Lot 16, Alabaster, Villa Esmeralda	-	1.16	ABSENCE	ABSENCE	< 1
BRGY. DITA							
11/05/2020 13:48	S20-7420	Block 24 Lot 2, New Santa Rosa Homes	7.75 / 28.9	0.26	ABSENCE	ABSENCE	< 1
11/05/2020 14:10	S20-7421	Block 19 Lot 11, New Santa Rosa Homes	7.78 / 29.1	0.20	ABSENCE	ABSENCE	< 1
11/05/2020 13:38	S20-7422	Water Tank, SolCar Ville Subdivision	7.77 / 27.8	0.48	ABSENCE	ABSENCE	< 1
11/05/2020 13:28	S20-7423	Block 3 Lot 7, SolCar Ville Subdivision	7.78 / 28.5	0.34	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis.

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna

CONTACT NO.: (049) 543-1916

WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
MDL: NA LOQ: NA	MDL: 0.06 LOQ: 0.20						
11/05/2020 13:00	S20-7424	#1780 National Road	7.66 / 28.5	0.38	ABSENCE	ABSENCE	< 1
11/05/2020 16:09	S20-7430	R & B Ice Plant, Inc.	7.86 / 29.5	0.36	ABSENCE	ABSENCE	< 1
11/10/2020 12:35	S20-7595	Clubhouse, San Lorenzo Royale	-	0.72	ABSENCE	ABSENCE	< 1
BRGY. DON JOSE							
11/11/2020 11:58	S20-7041	Science High School, Phase 1, Laguna Bel-Air	7.64 / 27.6	0.63	ABSENCE	ABSENCE	< 1
11/11/2020 11:43	S20-7043	Church, Block 108, Phase 5, Laguna Bel-Air	7.89 / 28.6	0.42	ABSENCE	ABSENCE	6
11/11/2020 12:19	S20-7042	Block 7 Lot 72, Phase 2, Laguna Bel-Air	7.46 / 28.3	0.20	ABSENCE	ABSENCE	< 1
11/11/2020 12:48	S20-7039	Block 47 Lot 12, Phase 4, Laguna Bel-Air	7.61 / 28.3	0.38	ABSENCE	ABSENCE	< 1
11/11/2020 15:00	S20-7717	8001, Pump 1, Acacia St., Santa Rosa Village I	-	0.56	ABSENCE	ABSENCE	< 1
11/11/2020 15:16	S20-7718	Clubhouse. Phase 4B, Santa Rosa Village I	-	0.38	ABSENCE	ABSENCE	< 1
11/11/2020 15:38	S20-7719	Clubhouse, Santa Rosa Village II	-	-	ABSENCE	ABSENCE	< 1
11/11/2020 15:59	S20-7720	Pump 9 & 10, Santa Rosa Estates I	-	-	ABSENCE	ABSENCE	< 1
11/11/2020 16:20	S20-7721	Clubhouse, Santa Rosa Estates I	-	-	ABSENCE	ABSENCE	< 1
11/11/2020 13:25	S20-7040	Drinking Fountain, Don Jose National High School	7.74 / 27.3	0.29	ABSENCE	ABSENCE	< 1
BRGY. MACABLING							
11/16/2020 15:00	S20-7793	Water Pump, Buena Rosa 9 Subdivision	7.63 / 28.9	0.11	ABSENCE	ABSENCE	< 1
11/16/2020 15:15	S20-7794	Block 4 Lot 26, Phase 2, Buena Rosa 9 Subdivision	7.50 / 29.8	0.08	ABSENCE	ABSENCE	< 1
11/16/2020 13:50	S20-7788	Water Pump, Corinthian Subdivision	7.71 / 29.0	0.77	ABSENCE	ABSENCE	< 1
11/16/2020 14:10	S20-7789	Block 11 Lot 19, Corinthian Subdivision	7.68 / 28.9	0.68	ABSENCE	ABSENCE	< 1
BRGY. MALITLIT							
11/05/2020 12:38	S20-7425	Clubhouse, Casan Residencia Subdivision	7.78 / 29.0	0.40	ABSENCE	ABSENCE	< 1
11/10/2020 11:58	S20-7596	Water Pump, Block 3 Lot 1, Phase 1A Annex, San Lorenzo Subd.	-	0.16	ABSENCE	ABSENCE	< 1
11/10/2020 12:04	S20-7597	Block 5 Lot 25, Phase 1A Annex, San Lorenzo Subd.	-	0.20	ABSENCE	ABSENCE	< 1
11/10/2020 12:17	S20-7600	Water Pump, Main Road, Phase 2, Terra Fortuna	-	0.13	ABSENCE	ABSENCE	75
11/10/2020 12:22	S20-7601	Block 11 Lot 16, Terra Fortuna	-	0.11	ABSENCE	ABSENCE	70
11/10/2020 11:34	S20-7598	Water Pump, 9999 W, Villa Las Casas	-	0.12	ABSENCE	ABSENCE	< 1
11/10/2020 11:42	S20-7599	Block 1 Lot 17, Villa Las Casas	-	0.08	ABSENCE	ABSENCE	< 1
11/05/2020 13:30	S20-7426	Drinking Fountain, Malitlit Elementary School	7.68 / 28.6	0.36	ABSENCE	ABSENCE	< 1

NOT VALID WITHOUT QR CODE



REVIEWED BY:

ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:

ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis.

ADDRESS: 8 North Science Avenue, Laguna Technopark Inc., Brgy. Biñan (Poblacion), Biñan City, Laguna
CONTACT NO.: (049) 543-1916
WEBSITE: www.lagunawater.com.ph

DATE/TIME COLLECTED	SAMPLE CODE	SAMPLE LOCATION	PARAMETER				
			pH/ Temperature ^A (- / °C)	RESIDUAL CHLORINE ^B (mg/L)	COLIFORM ^C		HPC ^D (CFU/mL)
					TOTAL (Coliforms/ 100mL)	FECAL/ <i>E. coli</i> (Coliforms/ 100 mL)	
BRGY. POOC							
11/10/2020 12:00	S20-7662	Water Pump, Villa Mercedes	7.36 / 27.8	0.14	ABSENCE	ABSENCE	1
11/10/2020 12:15	S20-7663	Block 2 Lot 1, Villa Mercedes	7.41 / 27.7	0.09	ABSENCE	ABSENCE	1
11/10/2020 14:00	S20-7667	Water Pump, Alinsod	7.66 / 27.4	0.48	ABSENCE	ABSENCE	15
BRGY. PULONG STA. CRUZ							
11/10/2020 13:28	S20-7593	Block 6 Lot 8, Buklod Diwa	-	0.89	ABSENCE	ABSENCE	< 1
11/10/2020 10:53	S20-7602	Drinking Fountain 1, Pulong Sta. Cruz Elementary School	-	0.52	ABSENCE	ABSENCE	100
11/10/2020 10:58	S20-7603	Wash Area, Pulong Sta. Cruz Elementary School	-	0.40	ABSENCE	ABSENCE	1
BRGY. SANTO DOMINGO							
11/11/2020 16:31	S20-7722	Clubhouse Santa Rosa Estates II	-	-	ABSENCE	ABSENCE	< 1

REMARKS: Sample collection was performed by LWC Field analyst/Laboratory technicians and were analyzed as submitted.

LEGEND: HPC – Heterotrophic Plate Count; CFU – Colony Forming Units; MDL – Method Detection Limit; LOQ – Limit of Quantification; NA – Not Applicable

DEVIATIONS: No deviation noted on sample collection and submission.


METHODS: A – Electrometric; B – Colorimetric; C – Enzyme Substrate; D – Pour Plate

METHOD REFERENCE: Standard Methods for the Examination of Water and Wastewater, 23rd Edition


NOT VALID WITHOUT QR CODE



REVIEWED BY:


ALYSSA MARIE C. PENALES, RMT
Microbiology Unit Manager (OIC)
License No(s). (PRC 0064969)

CERTIFIED CORRECT BY:


ANNA KARLA S. GUTIERREZ, RMT
Laboratory Services Manager
License No(s). (PRC 0060968)

This report may not be reproduced in part or in full and may not be used for advertisement or litigation purposes without permission from Laguna AAWater Corporation. This report is certified to have passed the Laguna AAWater Corporation Quality Control procedures for reporting results of analysis.